

PAGE: 1

PRINT DATE: 06/08/90

S050250L
ATTACHMENT
Page 28 of 152

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL HARDWARE
NUMBER: MO-AA1-435-X

SUBSYSTEM NAME: STABILIZED PAYLOAD DEPLOYMENT SYSTEM
REVISION : 2 06/08/90

	PART NAME VENDOR NAME	PART NUMBER VENDOR NUMBER
ASSEM :	MID MCA-1	V070-764610
ASSEM :	MID MCA-3	V070-764630
SRU :	RELAY, HYBRID	MC455-0135-0001
■ SRU :	RELAY, HYBRID	MC455-0135-0002

PART DATA

■ EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:

REFERENCE DESIGNATORS: 40V76A117 - K48
: 40V76A119 - K55

QUANTITY OF LIKE ITEMS: 2

■ FUNCTION:

THE RELAYS PROVIDE ON/OFF CONTROL OF THE Y₀ DRIVE MOTOR POWER FOR "BERTHING" THE PAYLOAD DURING GROUND OPERATIONS. HOWEVER THE "BERTH" FUNCTION COULD AGAIN BE REQUIRED SHOULD PAYLOAD DEPLOYMENT ON-ORBIT PROVE UNSUCCESSFUL. BOTH RELAYS, K48 AND K55, RESPOND TO COMMAND SIGNALS FROM SWITCH S36.

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE
NUMBER: MO-AA1-435-03

SUBSYSTEM: STABILIZED PAYLOAD DEPLOYMENT SYSTEM REVISION# 2 06/08/90
ITEM NAME: RELAY, HYBRID CRITICALITY OF THIS FAILURE MODE:2R3

■ FAILURE MODE:
SHORTED. ANY SINGLE SET OF CONTACTS.

MISSION PHASE:
00 ON-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY: 102 COLUMBIA
: 103 DISCOVERY
: 104 ATLANTIS
: 105 ENDEAVOUR

CAUSE:
PIECE PART STRUCTURAL FAILURE, CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL STRESS, PROCESSING ANOMALY

■ CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

■ REDUNDANCY SCREEN A) PASS
■ B) FAIL
■ C) PASS

PASS/FAIL RATIONALE:

- A) PRELAUNCH CHECKOUT
- B) ONE PHASE WILL NOT CAUSE MOTOR TO DRIVE - CANNOT CONFIRM RELAY FAILURE.
- C) PHYSICAL AND ELECTRICAL ISOLATION OF REDUNDANT ELEMENTS.

- FAILURE EFFECTS -

■ (A) SUBSYSTEM:
A SINGLE PHASE OF POWER WILL BE CONTINUOUSLY APPLIED TO A DRIVE MOTOR. WHENEVER THREE PHASE AC POWER IS PRESENT.

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE
NUMBER: MO-AA1-435-03

- (B) INTERFACING SUBSYSTEM(S):
THE DRIVE MOTOR COULD OVER HEAT AND FAIL. A FAILED MOTOR WOULD CAUSE A PEDESTAL FUNCTION TO BE AT HALF SPEED. IF THE RELAY FOR OPPOSITE MOTOR ROTATION IS ACTIVATED CIRCUIT BREAKER COULD TRIP.
- (C) MISSION:
NO EFFECT. FIRST FAILURE
- (D) CREW, VEHICLE, AND ELEMENT(S):
NO EFFECT - FIRST FAILURE
- (E) FUNCTIONAL CRITICALITY EFFECTS:
LOSS OF BOTH RELAYS IN THIS MODE RESULTS IN LOSS OF OUTBOARD YO DRIVE CAPABILITY WHICH CAUSES LOSS OF MISSION.

- DISPOSITION RATIONALE -

- (A) DESIGN:
REFER TO APPENDIX C, ITEM 1.
- (B) TEST:
REFER TO APPENDIX C, ITEM 1.

OMRSD: GROUND TURNAROUND
FREQUENCY OF CHECKOUT IS MISSION DEPENDENT.
DUAL MOTOR BERTH-TO-OUTBOARD FUNCTIONAL
S0790.A080-B
- (C) INSPECTION:
REFER TO APPENDIX C, ITEM 1.
- (D) FAILURE HISTORY:
REFER TO APPENDIX C, ITEM 1.
- (E) OPERATIONAL USE:
NO OPERATIONAL WORKAROUND AFTER SECOND FAILURE, HOWEVER, EVA IS AVAILABLE TO DRIVE PEDESTAL OUTBOARD.

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE
NUMBER: MO-AA1-435-03

- APPROVALS -

RELIABILITY ENGINEERING:	W. R. MARLOWE	<i>W.R. Marlowe</i>	<i>6/14/90</i>
DESIGN ENGINEERING :	T. TAUFER	<i>T. Tauffer</i>	<i>6/14/90</i>
QUALITY ENGINEERING :	M. F. MERGEN	<i>M. F. Mergen</i>	<i>6/14/90</i>
NASA RELIABILITY :		<i>G.E.</i>	<i>9/17/90</i>
NASA SUBSYSTEM MANAGER :			<i>9/25/90</i>
NASA EPD&C RELIABILITY :		<i>M. S. Dinsmore</i>	<i>for J. Woodard 9/18/90</i>
NASA QUALITY ASSURANCE :		<i>Phil Johnson</i>	<i>9/18/90</i>
NASA EPD&C SUBSYS MGR :		<i>J. R. Flaming</i>	<i>for F. Alaric 9/20/90</i>