

**FAILURE MODES EFFECTS ANALYSIS (FMEA) – NON-CIL HARDWARE
NUMBER: 05-6-2240 -X****SUBSYSTEM NAME: ELECTRICAL POWER DISTRIBUTION & CONTROL****REVISION: 1 07/26/99**

PART DATA

	PART NAME	PART NUMBER
	VENDOR NAME	VENDOR NUMBER
LRU	: PANEL A12	V070-730365
SRU	: SWITCH, TOGGLE	ME452-0102-7105

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:

SWITCH, TOGGLE, SPDT - STRUCTURE RETURN FOR FUEL CELL NO. 3

REFERENCE DESIGNATORS: 36V73A12S30**QUANTITY OF LIKE ITEMS: 1
ONE****FUNCTION:**

PROVIDES MANUAL CONTROL FOR CONNECTING FUEL CELL NO. 3 RETURN TO ORBITER STRUCTURE.

**FAILURE MODES EFFECTS ANALYSIS (FMEA) -- NON-CIL FAILURE MODE
NUMBER: 05-6-2240-02**

(B) INTERFACING SUBSYSTEM(S):

FOR SHORT ON INPUT SIDE OF SWITCH, ASSOCIATED CIRCUIT BREAKERS WILL TRIP AND CONTROL OF ALL FUEL CELL NO. 3 AND MAIN DC BUS C MOTOR SWITCHES WILL BE LOST. RESULTS IN LOSS OF REDUNDANCY (ABILITY TO REMOVE BUS LOAD) FOR SAFING FUEL CELL NO. 3. FOR SHORT ON LOAD SIDE OF SWITCH, NO EFFECT SINCE IT IS NOT OPERATED DURING FLIGHT.

(C) MISSION:

FIRST FAILURE - NO EFFECT

(D) CREW, VEHICLE, AND ELEMENT(S):

FIRST FAILURE - NO EFFECT

(E) FUNCTIONAL CRITICALITY EFFECTS:

SECOND FAILURE - LOSS OF REDUNDANT REACTANT VALVE CLOSURE CAPABILITY.
THIRD FAILURE (LOSS OF ESSENTIAL BUS 3AB) - POSSIBLE LOSS OF CREW/VEHICLE DUE TO INABILITY TO SAFE FUEL CELL NO. 3. LOSS OF ESSENTIAL 3AB BUS RESULTS IN LOSS OF FUEL CELL NO. 3 COOLANT PUMP, AS WELL AS REDUNDANT CONTROL OF ITS REACTANT VALVES. THIS NECESSITATES REMOVAL OF ALL LOADS FROM THE FUEL CELL IN ORDER TO RENDER IT SAFE. INABILITY TO REMOVE THE BUS LOAD FROM THE FUEL CELL UNDER THESE CIRCUMSTANCES WILL RESULT IN FUEL CELL OVERHEATING WITH SUBSEQUENT RUPTURE AND/OR EXPLOSION/FIRE.

- APPROVALS -

EDITORIALLY APPROVED
TECHNICAL APPROVAL

: BNA
: VIA APPROVAL FORM

: J. Kimura 7-26-99
: 86-CIL-025_05-6