

**FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL HARDWARE  
NUMBER: 05-6-2276 -X**

**SUBSYSTEM NAME: ELECTRICAL POWER DISTRIBUTION & CONTROL**

**REVISION: 1 07/26/99**

---

**PART DATA**

---

	<b>PART NAME VENDOR NAME</b>	<b>PART NUMBER VENDOR NUMBER</b>
LRU	: MDCA 1	V070-764200
LRU	: MDCA 2	V070-764220
LRU	: MDCA 3	V070-764230
SRU	: FUSE	ME451-0009-1005

---

**EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:**

FUSE, 15 AMP, AXIAL LEAD/CARTRIDGE TYPE - ESSENTIAL BUS MDCA TO MPCA

**REFERENCE DESIGNATORS:** 40V76A31F3  
40V76A32F3  
40V76A34F3

**QUANTITY OF LIKE ITEMS: 3**  
THREE-ONE PER MDCA

**FUNCTION:**

PROVIDES CIRCUIT PROTECTION BETWEEN AN ESSENTIAL BUS LOCATED IN THE MAIN DC DISTRIBUTION ASSEMBLY TO THE ONE IN THE MID PCA.

**FAILURE MODES EFFECTS ANALYSIS FMEA -- NON-CIL FAILURE MODE**

NUMBER: 05-6-2276- 01

REVISION#: 1 07/26/99

SUBSYSTEM NAME: ELECTRICAL POWER DISTRIBUTION &amp; CONTROL

LRU: MDCA 1, 2, 3

CRITICALITY OF THIS

ITEM NAME: FUSE

FAILURE MODE: 1R3

**FAILURE MODE:**

FAILS OPEN, FAILS TO CONDUCT

**MISSION PHASE:**

PL	PRE-LAUNCH
LO	LIFT-OFF
OO	ON-ORBIT
DO	DE-ORBIT
LS	LANDING/SAFING

<b>VEHICLE/PAYLOAD/KIT EFFECTIVITY:</b>	102	COLUMBIA
	103	DISCOVERY
	104	ATLANTIS
	105	ENDEAVOUR

**CAUSE:**STRUCTURAL FAILURE, CONTAMINATION, VIBRATION, MECHANICAL SHOCK,  
PROCESSING ANOMALY, THERMAL STRESS

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

<b>REDUNDANCY SCREEN</b>	A) PASS
	B) PASS
	C) PASS

**PASS/FAIL RATIONALE:**

A)

B)

C)

**- FAILURE EFFECTS -****(A) SUBSYSTEM:**

LOSS OF POWER TO THE ESSENTIAL BUS IN ONE OF THE THREE MID PCA'S.

**FAILURE MODES EFFECTS ANALYSIS (FMEA) – NON-CIL FAILURE MODE  
NUMBER: 05-6-2276- 01**

**(B) INTERFACING SUBSYSTEM(S):**

LOSS OF ESSENTIAL BUS POWER TO FUEL CELL CONTROLLER, COOLANT PUMP AND REACTANT VALVES NECESSITATING CREW ACTION TO DISCONNECT FUEL CELL FROM ASSOCIATED MAIN DC BUS.

**(C) MISSION:**

FIRST FAILURE - NO EFFECT

**(D) CREW, VEHICLE, AND ELEMENT(S):**

FIRST FAILURE - NO EFFECT

**(E) FUNCTIONAL CRITICALITY EFFECTS:**

SECOND FAILURE - LOSS OF REDUNDANT REACTANT VALVE CLOSURE CAPABILITY. AFTER THIRD FAILURE (MOTOR SWITCH CONNECTING FUEL CELL TO MAIN DC BUS LOADS FAILS CLOSED) MAY CAUSE POSSIBLE LOSS OF CREW/VEHICLE DUE TO INABILITY TO SAFE FUEL CELL. LOSS OF FUEL CELL COOLANT PUMP AND REACTANT VALVE REDUNDANT CONTROL NECESSITATES REMOVAL OF ALL LOADS FROM THE FUEL CELL IN ORDER TO RENDER IT SAFE. INABILITY TO REMOVE THE BUS LOAD FROM THE FUEL CELL WILL RESULT IN FUEL CELL OVERHEATING WITH SUBSEQUENT RUPTURE AND/OR EXPLOSION/FIRE.

---

**- APPROVALS -**

---

EDITORIALLY APPROVED  
TECHNICAL APPROVAL

: BNA  
: VIA APPROVAL FORM

: J. Kamisa 7-26-99  
: 96-CIL-025\_05-8