

SHUTTLE CRITICAL ITEMS LIST - ORBITER

SUBSYSTEM :ELECT POWER DIST & CONT FMEA NO 05-6 -2613 -1 REV:05/03/88

ASSEMBLY :PANEL MA73C	CRIT.FUNC: 1R
P/N RI :MC454-0032-3030	CRIT. HDW: 2
P/N VENDOR:	VEHICLE 102 103 104
QUANTITY :4	EFFECTIVITY: X X X
:FOUR	PHASE(S): PL LO X OO X DO X LS
:	

PREPARED BY:	REDUNDANCY SCREEN: A-PASS B-PASS C-PASS
DES R PHILLIPS	APPROVED BY:
REL M HOVE	SSM <i>W.C. Stang 5/14/88</i>
QE J COURSEN	REL <i>DD [Signature] 5/14/88</i>
	QE <i>B. Conner 5/14/88</i>

ITEM:

CIRCUIT BREAKER, 3 PHASE, 3 AMP - AC1 BUS FEED TO MID MCA 1, AC2 BUS FEED TO MID MCA 2, AC2 AND AC3 BUS FEEDS TO MID MCA 4

FUNCTION:

PROVIDES OVERCURRENT PROTECTION FOR 3 PHASE FEEDER CIRCUITS FROM AC1, AC2 AND AC3 BUSES TO MIDBODY MOTOR CONTROL ASSEMBLIES (MCA'S) 1, 2 AND 4, FOR VENT DOOR, PAYLOAD BAY DOOR, KU-BAND ANTENNA DEPLOY/STOW, RADIATOR DEPLOY/LATCH, REMOTE MANIPULATOR DEPLOY/LATCH AND PAYLOAD RETENTION LATCH MOTORS. 85V73A129CB2, CB7, CB9 AND CB13

FAILURE MODE:

FAILS OPEN, FAILS TO CLOSE, FAILS TO CONDUCT

CAUSE(S):

STRUCTURAL FAILURE, MECHANICAL SHOCK, THERMAL STRESS, VIBRATION, CONTAMINATION, PROCESSING ANOMALY

EFFECT(S) ON:

(A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE (E)FUNCTIONAL CRITICALITY EFFECT:

- (A) LOSS OF AC VOLTAGE TO AFFECTED CIRCUIT.
- (B) LOSS OF INTERFACE REDUNDANCY. NO EFFECT FIRST FAILURE - THE REDUNDANT MOTOR SUPPLIED BY ANOTHER CIRCUIT BREAKER COMPLETES..... FUNCTION.
- (C) POSSIBLE EARLY MISSION TERMINATION DUE TO LOSS OF PAYLOAD BAY DOOR CLOSURE REDUNDANCY.
- (D) FIRST FAILURE - NO EFFECT.

SHUTTLE CRITICAL ITEMS LIST - ORBITER

UBSYSTEM :ELECT POWER DIST & CONT FMEA NO 05-6 -2613 -1 REV:05/03/88

EFFECT(S) ON (CONTINUED):

(A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE (E) FUNCTIONAL
CRITICALITY EFFECT:

(E) POSSIBLE LOSS OF CREW/VEHICLE AFTER SECOND FAILURE (LOSS OF
REDUNDANT MOTOR OR POWER/CONTROL CIRCUIT) DUE TO INABILITY TO CLOSE
PAYLOAD BAY DOORS (RESULTING IN AERODYNAMIC STRUCTURAL DAMAGE DURING
ENTRY) AND/OR TO OPERATE VENT DOORS DURING DESCENT (DOOR FAILED CLOSED
RESULTS IN VEHICLE STRUCTURAL DAMAGE DUE TO PRESSURE DIFFERENTIALS).
LEFT AND RIGHT VENT DOORS ARE NOT CONSIDERED TO BE REDUNDANT TO EACH
OTHER. "B" SCREEN PASSES SINCE THE FAILURE CAN BE DETECTED BY CREW
MONITORING MECHANISM OPERATION TIMES.

DISPOSITION & RATIONALE:

(A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY (E) OPERATIONAL USE

A, B, C, D) DISPOSITION AND RATIONALE

REFER TO APPENDIX D, ITEM NO. 1 - CIRCUIT BREAKER

B) GROUND TURNAROUND TEST

VERIFY CIRCUIT BREAKER CLOSED BY MONITORING MOTOR CURRENTS (ALL THREE
PHASES) DURING VENT DOOR CLOSE TO OPEN AND OPEN TO CLOSE TESTS. TEST
WILL BE PERFORMED FOR ALL FLIGHTS.

E) OPERATIONAL USE

CONSIDERATION WILL BE GIVEN TO STOWING MECHANISMS WITH THE LOSS OF
REDUNDANCY. LOSS OF REDUNDANT PAYLOAD BAY DOOR CLOSE CAPABILITY
INVOKES A MINIMUM DURATION FLIGHT. FOR LOSS OF REDUNDANT VENT DOOR
OPEN CAPABILITY, OPEN VENT DOORS PRIOR TO ENTRY.