

Subsystem:	HPOTP B500 - 4750000-700	Critical Item List	Page:	42
Functional Assy:	Drive Turbine Section B50002	Prepared by: M.T. Spencer	Issue Date:	December 23, 1993
		Approved by: R.L. Pugh	Rev. Date:	December 08, 1995
		CIL Item: 0202		
CIL Item Code:	0202		Analyst:	M.T. Spencer
FMEA Item Code:	0202		Approved by:	R.L. Pugh
Function:	Separate Inlet/Exit		Rev. No.:	
System/Subsystem:	HPOTP B500 - 4750000-700		Rev. Date:	December 08, 1995
			Effectivity:	
			Hazard Ref.:	See Listings Below
Operating Phase	Failure Mode, Description and Effect		Criticality	
Operating Phase: a	Failure Mode: Loss of separation with resultant leakage.		Criticality:	1R
	Failure Cause(s):		Hazard Ref.:	A) C1S/M (AT) 1B2.1.1.1.1.1, 1B2.1.1.1.3, 1B2.1.1.1.4
	A. 1/n 80 ASO Fracture of bellows, or damage of the seal surface due to vibration, thermal growth, over temp, excessive loads, or material/mfg defect.		B) C1S/A/M/C (AT) 1A1.1.6.1.2, C1S/M (AT) 1B2.1.1.1.1.1, 1B2.1.1.1.3, 1B2.1.1.1.4	
	B. 1/n 108 or 124 Fracture of the bellows seals between the preburner and inlet heg. due to vibration, thermal growth, or material/mfg defect.		C) C1S/M (AT) 1B2.1.1.1.1.1, 1B2.1.1.1.3, 1B2.1.1.1.4	
	C. 1/n 058 Fracture of the main turbine housing (TOVS) due to vibration, thermal growth, excessive loads, or material/mfg defect			
	Failure Effect: Turbine inlet flow loss reduces turbine power output, and pump output with reduced engine thrust. This is sensed by the controller, which increases oxidizer preburner flow. Excess turbine discharge temperature will cause redline shutdown.			
	System: Engine shutdown			
	Mission/Vehicle: Mission scrub.			
	Loss of vehicle due to HPOTP turbine failure may result if not detected.			
	Redundancy Screens: A: Pass. Redundant hardware items are capable of checkout during normal ground turnaround. B: Pass. Loss of a redundant hardware item is detectable during flight C: Pass. Loss of redundant hardware items could not result from a single credible event.			
Operating Phase: m	Failure Mode: Loss of separation with resultant leakage.		Criticality:	1R
	Failure Cause(s):		Hazard Ref.:	A) C1S/M (AT) 1B2.1.1.1.1.1, 1B2.1.1.1.3, 1B2.1.1.1.4
	A. 1/n 80 ASO Fracture of bellows due to vibration, thermal growth, over temp, excessive loads, or material/mfg defect.		B) C1S/A/M/C (AT) 1A1.1.6.1.2, C1S/M (AT) 1B2.1.1.1.1.1, 1B2.1.1.1.3, 1B2.1.1.1.4	
	B. 1/n 108 or 124 Fracture of the bellows seals between the preburner and inlet heg. due to vibration, thermal growth, or material/mfg defect.			
	C. 1/n 058 Fracture of the main turbine housing (TOVS) due to vibration, thermal growth, excessive loads, or material/mfg defect			

Subsystem: HPOTP B500 - 4750000-700
Functional Assay: Drive Turbine Section B50002

Critical Item List
Prepared by: M.T. Spencer
Approved by: R.L. Pugh
CIL Item: 0202

Page: 43
Issue Date: December 23, 1993
Rev. Date: December 06, 1995

C) C1SM [AT] 1B2.1.1.f.1.1,
1B2.1.1.3, 1B2.1.1.4

Failure Effect:

Turbine inlet flow loss reduces turbine power output, and pump output with reduced engine thrust. This is sensed by the controller, which increases oxidizer preburner flow. Excess turbine discharge temperature will cause redline shutdown.

Systems:

Engine shutdown

Mission/Vehicle:

Mission abort.

Loss of vehicle due to HPOTP turbine failure may result if not detected

Redundancy Screens:

A: Pass. Redundant hardware items are capable of checkout during normal ground turnaround.

B: Pass. Loss of a redundant hardware item is detectable during flight

C: Pass. Loss of redundant hardware items could not result from a single credible event.

Subsystem: HPOTP B500 - 4750000-700 Functional Assy: Drive Turbine Section B50002		Critical Item List Prepared by: M.T. Spencer Approved by: R.L. Pugh CIL Item: 0202	Page: 44 Issue Date: December 23, 1983 Rev. Date: December 08, 1985
Part Name/No.	Design Considerations	Document Ref	
In 080 Inlet bellows	<p>FAILURE CAUSE A. The primary function of the bellows is to compensate for the relative deflections between the preburner and turbine inlet due to thermal, pressure, and mechanical loads. It also serves as a pressure vessel between the preburner and the turbine exhaust.</p> <p>The bellows mates with the preburner on the fwd side with gaskets, and to the outer case on the aft side.</p> <p>The bellows is PWA-SP 1143 (Incoloy 908) which was selected for its resistance to hydrogen embrittlement and low alpha which reduces thermal stresses. This is a fully machined bellows to eliminate welds and improve life.</p> <p>This part meets CEI LCF requirements, but does not meet the Fracture Mechanics Life, so a life limit and inspection requirement is imposed (DAR 0183)</p>	DAR NO. 0183	
In 108, & 124 Bellows seals	<p>FAILURE CAUSE B. The G2 flange seals were redesigned to reduce the amount of compression and load induced on the bellows. This redesign involved replacing the very stiff, low deflection Rockordyne Omega seals with the higher deflection E-seals. With the redesigned seals incorporated, the amount of compression and loading is decreased while the E-seals maintain adequate compression.</p> <p>This part meets CEI requirements.</p>		
In 059 Main turbine housing	<p>FAILURE CAUSE C. The Turbine Outer Vane Support (TOVS) transfers the loads from the inlet housing and turbine vane to the outlet duct. It also serves as a pressure vessel between the preburner and the turbine exhaust.</p> <p>The circumferential load imparted by the 1st stage ring is reacted thru the TOVS housing to pins in the pump-side flange.</p> <p>Material used is PWA-EP 1674 (IN 100), which was selected for its high strength in elevated temperature hydrogen.</p> <p>This part does not meet CEI requirements, so life and inspection limits have been imposed (DAR 0184).</p>	DAR NO. 0184	

Subsystem: HPOTP B500 - 4750000-700	Functional Assy: Drive Turbine Section B50002	Critical Item List Prepared by: M.T. Spencer Approved by: R.L. Pugh CIL Item: 0202	Page: 45 Issue Date: December 23, 1993 Rev. Date: December 08, 1995
Inspection and Test			
Possible Causes	Significant Characteristics	Inspection and Test	Document Ref
Failure Cause A In 060 Inlet bellows	Material Integrity	Material integrity is verified per specification requirements.	PWA-SP 1143
	Heat Treat	Heat treat is verified per specification, and drawing requirements.	PWA-SP 11-32, PWA-SP 1143
	Braze Integrity	Braze integrity is verified per specification.	PWA-SP 19
	INSPECTION		
		Produce slots for locking keys per specification.	REI 006
	Raw Material	Burin at the detail level per QAD	
	Finished Material	Burin - Cross Drilled Holes Only per QAD	
		ECI at the detail level per QAD ECI at the assembly level per QAD	SP-ECM Master SP-ECM Master
		FPI at the detail and assay level per QAD	SP-FPM Master
		X-ray per QAD	SP-XRM Master
	In-Process Testing	Proof pressure test to verify specification requirements.	REI 005
Failure Cause B In 108 & 124 Bellows seals	Material Integrity	Material integrity is verified per specification requirements.	PWA-SP 1143
	Heat Treat	Heat treat is verified per specification, and drawing requirements.	PWA-SP 11-3, PWA-SP 1143
	Plating Integrity	Nickel plating is verified per specification.	AMS 2424
	INSPECTION		
	Finished Material	FPI per QAD	SP-FPM Master

Subsystem: HPOTP B500 - 4750000-700
Functional Asy: Drive Turbine Section B50002

Critical Item List
Prepared by: M.T. Spencer
Approved by: R.L. Pugh
CIL Item: 0202

Page: 48
Issue Date: December 23, 1993
Rev. Date: December 08, 1995

Failure Cause C
fn 050
Main turbine bkg

Material Integrity

Material Integrity is verified per specification requirements.

PWA-SP 1074

All Cause

Failure Cause C
fn 050
Main turbine bkg

INSPECTION

Raw Material

Bonic - housing per QAD

Finished Material

FPI - at the detail or assembly level per QAD

SP-FPM Master

ECL - at the assembly level per QAD

SP-ECL Master

General Quality Requirements:

Supplier Quality Assurance requirements are included in PW-QA-8078, and include such requirements as first piece layouts. This requires the documentation of dimensions on all characteristics represented on the delivered article.

PWA-SP 300

Inspection Methods Sheets for use in the inspection of purchased parts and assemblies contain the necessary information to insure that the requirements of the QADs, engineering drawings, and referenced documents are satisfied. For shop fabricated parts, the sheets are audited by Inspection Methods.

The purchase orders for vendor supplied parts must comply with PWA-SP 300, 'Control of Materials Processes and Parts', which requires the vendor to provide material, process, and dimensional information to the Quality Department.

Acceptance

Acceptance test will be conducted as required by contract, to demonstrate specified performance.

DR SE-13

All Cause
fn : 060 Bellows,
058 TCVS

Welders

The bellows meets CEI LCF life but does not meet Fracture Mechanics life so a life limit and inspection requirement is imposed (DAR 0183).

DAR NO. 0183

The TCVS does not meet CEI life requirements, so a life limit and inspection requirement has been imposed (DAR 0184).

DAR NO. 0184