

SAA01FS030-013

MAY 27 1994

B/L: 245.00

SYS: APS

ROTATING
MECHANISM

Critical Item: Gear Coupling (2 Items Total)

Find Number: None

Criticality Category: 2

SAA No: 01FS030-013

System/Area: APS Rotating Mechanism/
HMF Bldg. M7-961

NASA
Part No: None

PMN/
Name: H70-1252/Mechanism,
APS Rotating, HMF

Mfg/
Part No: Dodge Div. Reliance
Elec. Co./Poweralign
3 1/2P

Drawing/
Sheet No: 79K07781/M-1

Function: Transfers torque from the Speed Reducer to the aft cradle rotation pin.

Critical Failure Mode/Failure Mode No: Disengages. /FM No. 01FS030-013.002

Failure Cause:

- Structural failure of the gear hubs or sleeve.
- Key shears.

Failure Effect: Loss of the drive/hold capability. The APS Pod/Cradle assembly may accelerate about the rotation axis, wrapping and stretching the GSE electrical cables around the APS Pod/Cradle assembly, causing damage to the TPS and/or the flight half electrical connectors. Detection method is visual and time to effect is immediate.

ACCEPTANCE RATIONALE

Design:

- The coupling is rated at 12,075 ft.- lbs. torque. The applied load is 4200 ft.- lbs.
- Gearing design complies with American Gear Manufacturers Association (AGMA) standards.

Test:

- None is performed.

WORKSHEET 5312-013
940517aoPS0132

*Attachment
5050239 LP
Sheet 14 of 20*

MAY 27 1994

Inspection:

- A visual inspection of the keys is performed annually per OMI V6C49. The keys are replaced if there are indications of deformation.

Failure History:

- The PRACA database was researched and no failure data was found on this component in the critical failure mode.
- The GIDEP failure data interchange system was researched and no failure data was found on this component in the critical failure mode.

Operational Use:

- **Correcting Action:**

There is no action which can be taken to mitigate the failure effect.

- **Time Frame:**

Since no correcting action is available, time frame does not apply.