

NAME P/N QTY	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE

103FM10Z				
FABRIC ATTACHMENT RING ITEM 103 (1) LEFT (1) RIGHT	2/2	Jammed open or mated with arm bearing or sizing ring.	END ITEM: Unable to lock or unlock fabric attachment ring to/from sizing ring or arm bearing.	A. Design - The fabric attachment ring is made of 7075-T73 Aluminum Alloy and is finished with Type II CLI anodize. All surfaces have a 63 finish. The locking system consists of two spring loaded sequential locks and one manual lock. The locking latches are made of 7075-T73 Aluminum Alloy and the spring and retaining screws are made of stainless steel. The threaded portion of the fabric attachment ring is designed for "one way" initiation of threaded engagement to ensure proper alignment and locking.
----- 10145-05 (2)		Defective material; latch, spring or sizing ring. Foreign matter in latch.	GFE INTERFACE: Unable to assemble or disassemble fabric attachment ring to/from sizing ring or arm bearing.	Normal rotation loads result in arm bearing rotation which precludes torque induced loads into the fabric attachment rings. The threaded protion of the fabric attachment ring is coated with a dry film lubricant to allow smooth travel of the ring when being mated.
		MISSION: Terminate EVA prep. Loss of EMU use for designated crewmember.		B. Test - Acceptance: The fabric attachment ring is subjected to testing per ATP 10145 at Airlock with ILC source verification.
		CREW/VEHICLE: None.		PDA: The following tests are conducted at the Lower Arm level in accordance with ILC Document 0111-710112: 1. Initial leak test at 4.3 +/- 0.1 psig to verify leakage les than 6.0 scc/min. 2. Proof pressure test at 8.0 + 0.2 - 0.0 psig to verify no structural damage. 3. Post-proof pressure leak test at 4.3 +/- 0.1 to verify leakage less than 6.0 scc/min. 4. Final leak test at 4.3 +/- 0.1 psig to verify leakage less than 6.0 scc/min.
		TIME TO EFFECT /ACTIONS: Minutes.		Certification: The fabric attachment ring was successfully tested manned during SSA certification to duplicate 458 hours operational life (Ref. ILC Report 0111-711330).
		TIME AVAILABLE: N/A		The following usage, reflecting requirements of significance to the fabric attachment ring, was documented during certification.
		TIME REQUIRED: N/A		Requirement S/AD Actual ----- Elbow Cycles 49660 102000
		REDUNDANCY		Engage/Disengage 300 800
		SCREENS:		Don/Doff 98 400
		A-N/A		Pressure Hours 458 916
		B-N/A		
		C-N/A		C. Inspection - Components and material manufactured to ILC requirements at an Approved Supplier are documented from procurement through shipping by the supplier. ILC incoming receiving inspection verifies that the materials received are as identified in the procurement documents, that no damage has occurred during shipment and that supplier certifications have been received which provides traceability information.

The following MIPs are performed during the arm assembly manufacturing process

NAME P/N QTY	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
		103FM10Z		<p>to assure that the failure causes are precluded from the fabricated item:</p> <ol style="list-style-type: none">1. Visually inspect static seal for damage.2. Visually inspect ring for scratches, burrs. <p>During PDA, the following inspections points are performed at the arm assembly level per ILC Document 0111-710112:</p> <ol style="list-style-type: none">1. Inspection for cleanliness to VC level.2. Visual inspection for damage, wear or material degradation.3. Visual inspection for damage following proof-pressure test. <p>D. Failure History - B-EMU-103-A038 (10/22/96). During installation of fabric attachment ring onto lower arm, manual lock button would not remain in open position. Found mating fabric restraint and bladder flanges bulge into button slot, pushing button back towards closed position. No corrective action taken.</p> <p>E. Ground Turnaround - Inspected for non-EET processing per FEMU-R-001, Pre-Flight Inspections and Final Structural and Leakage, SSA Connector Verification. None for EET processing. Additionally, every 4 years chronological time or 229 hours of manned pressurized time, the sizing ring is disassembled, cleaned, inspected, lubricated and reassembled.</p> <p>F. Operational Use - Crew Response - Pre EVA/Post EVA: Trouble shoot problem, Consider use of third EMU. If no success terminate EVA prep. EMU is no go for EVA. EVA: When CWS data confirms SOP activation, abort EVA.</p> <p>Training - Standard training covers this failure mode.</p> <p>Operational Consideration - Flight rules define go/no go criteria related to EMU pressure integrity and regulation. EVA checklist procedures verify hardware integrity and systems operational status prior to EVA. Real Time Data System allows ground monitoring of EMU systems.</p>

EXTRAVEHICULAR MOBILITY UNIT
SYSTEMS SAFETY REVIEW PANEL REVIEW
FOR THE
I-103 ARM ASSEMBLY
CRITICAL ITEM LIST (CIL)

EMU CONTRACT NO. NAS 9-97150

Prepared by: *J. Chumley* 3/27/02
HS - Project Engineering

Approved by: *SRE* 12/04/02
NASA-SSA/SSM

M. Snyder
HS - Reliability

R. Blaw 5/14/02
NASA-EM/SSM

Alan H. Poyel for EMU
HS - Engineering Manager

J. Funt 5/17/02
NASA-SSM

A. H. Huber 5/23/02
NASA-MOD

Joe Turner 6/04/02
NASA-EM/SSM

B. Ahn 6/04/02
NASA-Program Manager