

CIL
END CRITICAL ITEMS LIST

Page: 1
Date: 12/02/91

12/24/91 SUPERSEDES DM 11/90

FINAL TEST

NAME P/N QTY	ENR	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
CAUTION AND WARNING SYSTEM, ITEM 15A SU785970-13 (1)	2/2	ISO10181: BITE circuit fails (COMP.)	END ITEM: BITE Indicator on DCW is continuously on. CAUSE: Electronic component failure.	A. Design - Established reliability capacitors and resistors are qualified to applicable military standards and thermal shock per Condition B Test Method 107 of MIL-STO-202. Microcircuits are qualified to the requirements of MIL-M-38510 and receive the burn-in of Class A parts per Method 5804 of MIL-S10-803. Transistors, diodes are qualified to the requirements of MIL-S-19500 and receive the burn-in of JARENV level parts per the applicable Methods, 103B, 103D, 104D of MIL-S10-750. The electronic components are operating within the power derating requirements of SWS7204. The printed (PC) boards are fiberglass/epoxy per MIL-P-13949 type of and manufactured in accordance with SR-N-0006. Parts mounting and soldering is per MSFC-S10-136 and MHS5300.4 (JN-1). The CWS is a mother/daughter board assembly. The daughter boards are held in place by metal card guides which also provide thermal transfer from the boards to the CWS case. The top cover of the CWS exerts a downward force on the daughter boards to keep them properly seated in the mother board connectors. Flex tape (Kapton insulated, flexible flat conductor) instead of conventional Teflon coated wires is used to provide connections between the mother board and the external connectors. This prevents pinching of the conductor during item assembly. The PC board assemblies are conformal coated per MIL-A-46146 (Dow Corning RTV 314B) for environmental and humidity protection. Electrical connectors are environmentally sealed to prevent damage due to contamination and humidity.

用，Teat

Concurrent Acceptance Test

full functioning of the ODS is verified during Item A10 Tests included continuity, logic flow, x-state sequencing, fault simulation, verification of status and fault messages, warning and alert tones activation, and BITE activation. These tests are conducted upon completion of random vibration test (6.1 arm).

EPA Lett

The above electrical tests are repeated during PSS PBA to verify CWS operation. The CWS is also operational during

SEIU-44-001H
Page 1071

CIL
EMU CRITICAL ITEMS LIST

Pages 2
Date 12/12/91

12/24/91 SUPERSEDES 06/31/90

ANALYST:

NAME	FAILURE	MODE &	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
P/N	CAUSES			
REV	CRIT			

2/2 15BFM10:

either PLSS PDA electrical tests such as sensor accuracy checks, Item 123 Fan Operation, Item 174 RPS checkouts, and Solenoid Valve Activation.

Certification Test -

The item completed the 15 year structural vibration and shock certification tests during 10/83. EC's 42806-244 (add Jumper wires, add diode CR221, change resistor R301), 42806-365-3 (eliminate interferences with PLSS), 42806-715 (overstrained resistor R503 due to an improper interface circuit in the delta trigger GFE, software change, diode VR281 rewiring) 42806-942 and 42806-942-1 (transistor S201 lead stress relief) have been incorporated and certified by similarity or analysis since this configuration was tested.

Checkout Test -

Proper operation of the CWS is verified during electrical PIA tests per JEMU-R-001 during such tests as Transducer and DCM Gauge Calibration Check (RPPIA). A full CMS logic Test is performed a minimum of one every two years per JEMU-R-001, CMS Logic Flow Test.

C. Inspection -

Each circuit board, the flex tape, and connectors are inspected for damage and contamination prior to being placed into finished stores. The CMS assembly is inspected internally and externally for damage and contamination during item assembly and externally during ATP. All soldering is inspected by NS QA and NCAS QA per MMPS300.4 (3A-1).

D. Failure History -

J-EMU-150-AB01 (7-16-85) During PIA testing, several failures occurred: BITE light did not come on after power switch over as required, CMS failed the entire Logic Flow Test, and BITE failed the Tone Test. The BITE light failure was due to a short circuit in the flex tape between battery power discrete and BITE light control lines. The Logic Flow and Tone test failures were due to a faulty EEPROM in the CMS. Both the flex tape assembly and the faulty EEPROM were replaced. Additional tests were added to the CMS JPF and PDA via EC 42806-886.

H100159
2701 Page 4-4-1000

CII
EMU CRITICAL ITEMS LIST

Page: 3
Date: 12/02/91

12/24/91 SUPERSEDES 08/31/90

ANALYST:

NAME	FAILURE	MODE & CAUSED	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
2/2	150FM10;			E. Ground Turnaround - Tested per EEMU-A-001, bite light verification. F. Operational Use - CRM Response Pre/Post EVA: Verify status list operational. EMU go for EVA. Consider EMU 3 if available. EVA: Verify status list operational. Continue EVA. Rely on tone for future bite failure warning. Training: Standard training covers this failure mode. Operational Considerations: Flight rules define EMU go/no-go criteria related to this. EVA checklist procedures verify hardware integrity and systems operational status prior to EVA. Real Time Data System allows ground monitoring of EMU systems.