

CRITICAL ITEMS LIST

12/24/91 SUPERSEDES 01/02/90

Page: 1
Date: 12/02/91

NAME	P/N	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	ANALYSIS
ELECTRICAL POWER HARNESS, ITEM 151	897809151-4	2/IR	ITEM 151 P9 connector disengages from battery connector.	END ITEM: P9 connector detached from battery connector.	A. Design - The snap ring that holds the P9 connector in place on the PLSS is captured within a counterbored usher that prevents it from coming out of the connector groove once assembled.
	(1)				B. Test - Component Acceptance Test - The P9 connector on the Item 151 harness is subjected to a visual examination during the EOP portion of acceptance testing to insure there is not any damage which would prevent proper installation at the PLSS level.
					PDA Test - The P9 connector as assembled to the PLSS is fit checked and functionally checked to a battery during PDA testing to insure proper P9 connector mounting.
					Certification Test - This item has completed the 15 year structural vibration and shock certification requirements during 10/85. EC's 42806-527-2 (insulation resistance check during Full Test) and 42806-865 (remove clamp splices) have been incorporated and certified by test since this configuration was certified.
					During harness manufacturing the following inspections are performed: The P9 connector is visually inspected at incoming inspection as a detail and after assembly of the adapter ring to insure it meets the specified requirements.
					E. Failure History - The following ADT's were issued for the Item 151 due to improper P9 connector installation: J-EMU-151-001 (2-11-82) - During visual examination, it was found that the P9 connector was loose as attached to the PLSS and would not allow proper mating to the battery. This was due to a missing snap ring which is supposed to lock the connector in place on the PLSS structure. The corrective action replaced the harness with a new design configuration, per EC 42806-196, to prevent the snap ring from moving out of place once assembled.

CRITICAL ITEMS LIST

12/24/91 SUPERSEDES 03/02/90

ANALYST:

Page: 2
Date: 12/02/91

NAME	P/N	QTY	CR#	FAILURE MODE	CAUSES	FAILURE EFFECTS	RATIONALE FOR ACCEPTANCE
			2/90	IS1FM171			

E. Ground Turnaround -
Tested per EMU-R-001, pre-flight X-state verification with flight battery.

F. Operational Use -
Crew Response -
PreEVA/PostEVA; Troubleshoot problem. Consider third EMU if available. If no success, EMU go for SCU standby.
EVA: When loss of fan, com and OMS data occurs, open helmet purge valve and deactivate EMU power. Terminate EVA.
Training -
Standard training covers this failure mode.
Operational Considerations -
EVA checklist procedures verify hardware integrity and system operational status prior to EVA. Real Time Data System allows ground monitoring of EMU systems. Flight rules define go/no go criteria related to EMU battery power.