

600 CALIFORNIA STONE LTD

480-31570 2004 RELEASE GPO:2002/MAR

Page: 1
Date: 09/24/90

NAME	P/T	CIV	CDB	FAILURE MODE	CAUSED BY	FAILURE EFFECT	CRITERIA FOR ACCEPTANCE	
							DESIGN	TEST
PRESSURE TRANSDUCER, CIVN 215	2/100	205FM021		END TERM:			A. Design -	
				Continued			Shorting of the 215 wiring and strain gauge is prevented through the following design features. The transition between the gauges and the sensor header is accomplished through the use of an intermediate interconnect ring. The gauges are connected to the thick film ring pads through .001 inch diameter gold wire that is bonded at each end. The sensor header pins then pitch up the ring pads when the header is assembled in place. The sensor header module connection is achieved through short lengths of teflon coated 432 gauge wire. The material connector/electrodes interface is achieved through 824 gauge teflon insulated wire.	
80778472-6 (1)				Failure of internal electrical wiring or strain gauge due to an open or short circuit.		END INTERFACE: Loss of accurate BOP pressure reading. CIV will calculate too much time remaining for breathable air.	All inter connecting wires are kept as short as possible but with sufficient strain relief to prevent breakage. During assembly, all wiring can be visibly inspected once in place to insure they are not rubbing any edges.	
						MISSION: None. Fatal Indication that a rupture of BOP oxygen exists.	B. Test -	
							Component Acceptance Test - The pressure transducer output is checked at the vendor (Qualite Semiconductor Inc.) per section 10.7 (Error Band Test) of Acceptance Test Procedure ITP 215. This test consists of checking the transducer output at increments from 0 psig to 7400 psig and back to 0 psig at temperatures of 70 degrees F, 0 degrees F, and 100 degrees F.	
							Component Functional Calibration Test part A1-E-215 - The item is pressurized with a known pressure over the range of 0-7400 psig and 7400-0 psig. The output of the transducer when compared to the known pressure must be within 250 psig, except at 0 psig it shall be within 100 psig. An incorrect signal would be detected at this test.	
							B1-E-215 Functioning per 8040-54-007 - The item is checked for proper operation by pressurizing the end (use 4500 psig) to a known pressure of 7200-7400 psig. The psig is then allowed to bleed down at the rate of 5.26 - 3.44 before 802. The final pressure when compared to the known pressure shall be within 250 psig, except at 0 psig it shall be within 100 psig.	
							Certification Test - The item completed the 15 year structural vibration and shock certification requirement during 10/81. Engineering changes 42008-161 (Preclude the possibility of a cable entry failure), 42006-3D1 (Eliminate a potential interference between transducer and BOP).	

10
11
12

Digitized by srujanika@gmail.com

011
BUD CRITICAL FAILURE REPORT

09/01/99 APPROVED/DER 09/02/99

ANALYST:

Page: 2
Date: 01/02/00

NAME	FAILING
P/F	MODE 3
UNIT	CAUSES
8700	8700H001

FAILURE EFFECT

REQUIREMENT FOR ACCEPTANCE

42000-6TP (Added void inspection requirements and a more stringent leakage test) and 42000-600 (Added a voltage conditioning requirement and a more stringent screening procedure) have been incorporated and verified since this configuration was certified.

C. Inspection -

Units are subjected to the following test during assembly. The electronic components in the transducer network are screened to MIL-STD-883 and the hybrid assembly 8025-A-210 II receives burn-in and temperature cycle screen per MIL-STD-823A to ensure their operation reliability and circuit integrity.

The -4 and -5 are the same except for minor wiring changes to comply with MIL-STD-883 (3A-1), improved shield grounding to reduce EMI susceptibility, improved part traceability, and increased electronics burn-in time. The sensor is visually inspected during assembly to insure proper wire strain relief and that soldering conforms to MIL-STD-883 (3A-1).

1. Vendor Document (MIL-2543) Component Acceptance tape related electronic testing with specific conditions (10.3) Burn-In Test done at ambient temperature and pressure for (48) hrs. min. (10.4) insulation resistance test done at (100) VDC. (10.4) Power Consumption test done at (10.9) VDC.

2. Vendor Document (MIL-2667) Burn-In of Hybrid Circuit Temp Increase to 257 degrees F for 100 hours at board level. New Units P/F 87720173-3 will be subjected to the following inspections later during assembly.

3. Burn-in existing units.

4. Test performed on the amplifier level - Vendor Document - MIL-2667(3) temp cycle per MIL-STD-883 Method 1910 Condition C (MIL-2667) Burn-In per MIL-STD-883 Method 1015, Condition at 125 deg (2000/3) Stabilization per MIL-STD-883 Method 1000, Condition C.

D. Failure History -

2-00-213-001 (8-23-43) Transducer read full scale, the full scale reading was the result of an open circuit in the transducer electronics module. The open circuit was the result of a tilted gold lead wire ball free from one of the integrated circuit aluminum pads. The tilting of the gold ball connection was attributed to random contamination of

811
810 CRITICAL ITEMS LIST

09/01/89 SUPERSEDED 04/02/90

Page 3
Date: 01/12/90

NAME	FAILURE	CAUSE	FAILURE EFFECT	REASONS FOR ACCEPTANCE	
				DATE	TESTER
810	21910201				

the joint before joining. Bullets or sheets were changed to add a mandatory visual inspection of chips and bolts for cleanliness prior to joining field units H-081-005-0002 (10-7-81). Transducer read high during 20P PMA. High reading was caused by calibration at only one temperature by Bullets. The transducer was successfully recalibrated by Bullets. Bullets calibration procedure was revised to make calibration at all three calibration temperatures (H-10-100 9).

H-081-213-002 (11-14-85) the transducer had a high, erratic, reading. This high reading was the result of using the unit in an electromagnetic field of greater magnitude than the transducer design or test units. The present 20P requirement is being revised to a reduced 400 GRS requirement that accepts temporary 600 GRS induced mutagees.

H-081-213-002 (11-19-85) The transducer had damaged cable connector. This was the result of the use of Scotch Weld which made the cable attachment too rigid. The Scotch Weld will be deleted in all 4-6 configurations and subsequent. Related failures:

H-081-151-004 (4-22-87) Bullets circuit resistance too high. The high resistance was a result of the use of a fabricant on the interfacing connector shell surface. This prevented proper grounding of the mating connector. EC-42007-329-2 adds a grounding ring, provided by Bantam Corp., to all units. There is no impact on certification.

H-081-015-0004 (4-23-87) the electrical bonding between the sensor and copper manifold was not of specified height. This was the result of torque being applied between the mating surfaces during assembly. Assembly Operation sheets were revised to clarify areas of application.

6. Ground Penetrator:

Tested per FIMU-4-004, Transducer and 20P Gauge Calibration Check, verifies the 20P 600 pressure reading is within +/- 4% of the 20P gage (2132).

7. Operational use:

Cross Response:

EVA : Since EVA termination is required as soon as 20P is tested and this failure is not detectable, EVA termination would continue.

60
50
40

CH
THE OFFICIAL ITEM LIST

Page: 4
Date: 01/12/2019

PARTNER **EF-18** **EF-18** **EF-18** **EF-18**

PERFORMANCE FOR ACCEPTANCE

Spectral Training
Standard Training
Standard GCU training covers this failure mode.
Operational considerations:
GCU checklist procedures verify hardware integrity and
system operational status prior to GCU.
Flight rules dictate that no less than 10% to 15%
Real Time Data System allows ground monitoring of the
systems.

Page: 4
Date: 01/01/2014

EMU - 136B