

ITEMA
EMU FAILURE MODE, EFFECT ANALYSIS

01/02/90 SUPERSEDES / /

ANALYSIS:

Page: 1
Date: 03/10/90

NAME P/N CAT	FUNCTION	FAILURE MODE & CAUSES	MISSION PHASE	FAILURE EFFECT	FAILURE DETECTION FLIGHT/GROUND	TIME TO EFFECT/ ACTIONS	CRIT	REMARKS/ HAZARD	REF
PURGE VALVE, ITEM 314 04207027-3 (1)	The valve is used to initiate a suit purge when ventilation or cooling is lost during an EVA; or to purge the nitrogen from the suit during the EMU donning sequence.	14FM081a: fails to open, restricted flow. Causes: failure, button or plunger jamming, Condensation, inlet filter clogs, Temperature, freezing during EVA due to entrained water.	EVA	EMU ITEM: Unable to provide effective purge in the event suit cooling or ventilation is lost. GPE INTERFACE: unable to purge EMU with 314 valve. Helmet purge valve (1050) available for EMU purge.	FLIGHT: No. GROUND: Ref. TEMU-N-001, Para. 7.3.3.2.1.4. 14 DCM Purge Valve Actuation and Flow.	TIME 0-N/A AVAILABLE: N/A TIME REQUIRED: N/A	3/IR A-PASS 0-N/A C-PASS	The operation of the purge valve is verified during the a2 purge sequence. The filter is replaceable. The redundant path for this failure is the 1050 helmet purge valve. Valve is a standby item during EVA.	None.

HAZARD:
None for single
failure.

CREW/VEHICLE:
None for single
PLSS component
failure. None for
loss of helmet
purge valve
(1050). Possible
loss of crewman
with loss of 314
purge valve.

SD402269
ATTACHMENT -
PAGE 19 OF 30

SDMU-4
3