

PMEA NO. <u>4.2.6.2</u>	SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT <u>IVC/CLB</u> DWG NO. <u>2224819-506, 508/</u> <u>2224821-503</u> SHEET <u>1</u> OF <u>11</u>
FAILURE MODE AND CAUSE Loss of Iris Function (Mechanical). Loss of Zoom Function (Mechanical). Loss of focus Function (Mechanical). <u>CLB</u> - Motor Failure - Gear Train Failure - Lens Failure	FAILURE EFFECT ON END ITEM Inability to control focus, zoom, or iris. <u>Worst Case:</u> Loss of mission critical video.	RATIONALE FOR ACCEPTANCE DESIGN FEATURES The IVC/Lens Assembly is comprised of 16 electrical subassemblies; 13 subassemblies are RCA Astro designed and fabricated using standard printed-circuit board type of construction. The remaining three assemblies, high voltage power supply, oscillator, and stepper motors, are vendor supplied components which have been specified and purchased according to RCA Specification Control Drawings (SCDs) prepared by engineering and reliability assurance. Specifications per the SCD are prepared to establish the design, performance, test, qualification, and acceptance requirements for a procured piece of equipment. Parts, materials, processes, and design guidelines for the Shuttle CCTV program are specified in accordance with RCA 2295503. This document defines the program requirements for selection and control of FET parts. To the maximum extent, and consistent with availability, all parts have been selected from military specifications at the JAN level, as a minimum. In addition to the overall selection criteria, a subset of general purpose preferred parts has been defined by this document and the RCA Government Systems Division Standard Parts List. In the case of the CMOS and TTL family of microcircuits, devices are screened and tested to the MIL-STD-883C equivalent and procured under the designations of HI-REL/DHQ and SNC 54LS from RCA-SSD and Texas Instruments Corp, respectively. Parts not included in the above documents have been used in the design only after a nonstandard item approval form (NSIAF) has been prepared, submitted to Reliability Assurance Engineering (RAE) and approved for use in the specific application(s) defined in the NSIAF by NASA-JSC. <u>Worst-Case Circuit Analyses</u> have been performed and documented for all circuit designs to demonstrate that sufficient operating margins exist for all operating conditions. The analysis was worst case-in that the value for each of the variable parameters was set to limits that will drive the output to a maximum (or minimum). A component application review and analysis was conducted to verify that the applied stress on each piece part by the temperature extremes identified with environmental qualification testing does not exceed the stress derating values identified in RCA 2295503. In addition, an objective examination of the design was performed through a PDR and CDR to verify that the IVC/Lens assembly met specification and contractual requirements.

FMEA NO.	4.2.6.2	SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT	TVC/CLA
Criticality	2/2		Dwg No.	2294819-506, 508Z 2294821-503
Failure Mode and Cause			Sheet	2 OF 11
Loss of Iris Function (Mechanical). Loss of Zoom Function (Mechanical). Loss of Focus Function (Mechanical).	Inability to control focus, zoom, or iris. <u>Highest Case:</u> Loss of mission critical video.	<u>DESIGN FEATURES (Continued)</u> The general arrangement of the lens assembly is to provide an integrated housing, motor, and circuit board package which can accommodate various commercially available lenses. Emphasis is placed on accessibility of the lens, its drive components, and limit stops. Components within the lens assembly have been modularized, serving both the HIA, CLA, and HLA assemblies. The lens housing structure is a one-piece casting designed to minimize machining and provide a rugged dimensionally stable mounting for the optical components. The housing is in the form of a right angle. The vertical member interfaces with the front surface of the camera and the horizontal member supports the drive motors on the upper surface with the lens function circuit boards in a cavity on the underside.	<u>RATIONALE FOR ACCEPTANCE</u>	
MIA - Motor Failure - Gear Train Failure - Lens Failure		<u>Lens Function Drive Train</u> The iris, zoom, and focus drives are identical in concept; the only difference is the lower gear ratio in the iris train to provide the 2.8-second end-to-end travel capability necessary for the ALC operation. The table (on next page) shows the drive train parameters with overall torque margins for the three lens functions. The motor/gear heads are mounted on the lens housing rather than on the lens, to permit the desired lens interchangeability for the shuttle mission with minimum impact on the actual lenses. Various types of motors were considered for this application, trading off size, power, weight, control-circuit complexity, command capability, and qualification status. The brushless and stepper-motor types fit the package and power requirements, the latter being preferred because of its simplicity, reliability, and space-qualified status. The selected stepper motor (a size-8, Alnico-9 pole-piece, permanent-magnet stepper) is mated with a spur train gearhead. Both units are manufactured by Minco Motor Co. A 48-diametral-pitch (48-DPI) spur gear on the gearhead output shaft meshes directly with the gears which are a part of the zoom, focus, and iris ring functions on the lens gear.		

FMEA NO. <u>4.2.6.2</u>	SHUTTLE CCTV CRITICAL ITEMS LIST						UNIT <u>TVC/CLB</u>	
CRITICALITY <u>2/2</u>							DWG NO. <u>2294819-506, 508/ 2294821-503</u>	
FAILURE MODE AND CAUSE							SHEET <u>3</u> OF <u>11</u>	
Loss of Iris Function (Mechanical). Loss of Zoom Function (Mechanical). Loss of Focus Function (Mechanical).	Inability to control Focus, zoom, or iris.	RATIONALE FOR ACCEPTANCE						
CLB - Motor Failure - Gear Train Failure - Lens Failure	Worst Case: Loss of mission critical video.	DESIGN FEATURES (Continued)						
LENS DRIVE TRAIN PARAMETERS								
Drive	Component	Travel (degrees)	Time End-to-End (seconds)	Input Torque (oz-in)	Ratio No. or Teeth	Efficiency (%)	Loss Torque (oz-in)	Net Torque (oz-in)
Zoom	Motor			-	-	-	-	0.27
	Gearhead			0.27	78:1	80	3.7	18.4
	Gearhead				50		2.2	52.0
	Output Gear	150	6.6	18.4	156	96	10.0	Torque Margin 5.2:1
Focus	Lens Gear							
	Motor			-	-	-	-	0.27
	Gearhead			0.27	48:1	80	2.6	10.3
	Gearhead				50		1.3	30.0
Iris	Output Gear	262	7.5	18.3	156	96	10.0	Torque Margin 3:1
	Lens Gear							
	Motor			-	-	-	-	0.23
	Gearhead			0.27	48:1	80	2.6	10.3
	Gearhead				50		1.3	30.0
	Output Gear	105	2.8	18.3	156	96	5.0	Torque Margin 6:1
	Lens Gear							

FMEA NO. <u>4.2.6.2</u>	SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT <u>TVC/CLA</u> DWG NO. <u>2294819-506, 508/</u> <u>2294821-503</u> SHEET <u>4</u> OF <u>11</u>						
CRITICALITY <u>2/2</u>	<table border="1"> <thead> <tr> <th>FAILURE MODE AND CAUSE</th> <th>FAILURE EFFECT ON END ITEM</th> <th>RATIONALE FOR ACCEPTANCE</th> </tr> </thead> <tbody> <tr> <td> Loss of Iris Function (Mechanical). Loss of Zoom Function (Mechanical). Loss of Focus Function (Mechanical). CLA - Motor Failure - Gear Train Failure - Lens Failure </td><td> <u>Inability to control focus, zoom, or iris.</u> <u>Worst Case:</u> <u>Loss of mission critical video.</u> </td><td> <p><u>Harrow Angle Zoom Lens Assembly</u></p> <p>The lens utilized in the HLA and CLA is a 18 mm to 108 mm Canon varifocal (200mm) lens with a minimum f-stop of 1.6 to T-120 and a fully closed position. By design the lens selected after much evaluation was a high quality commercially available unit procured to a Shuttle CCTV specification.</p> <p>The vendor item is specified to include only materials and lubricants which meet the RCA and STS approved lists; and final cleaning, assembly, and lubrication is completed in the USA plant under RCA field quality controls.</p> <p>The lens has been exposed to developmental testing and qualification testing as required for the STS cable and cargo bay environments.</p> <p>This assembly has been used on all STS developmental and operational missions.</p> <p><u>QUALIFICATION TEST</u></p> <p>For Qualification Test flow, see Table 2 located at the front of this book.</p> </td></tr> </tbody> </table>	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE	Loss of Iris Function (Mechanical). Loss of Zoom Function (Mechanical). Loss of Focus Function (Mechanical). CLA - Motor Failure - Gear Train Failure - Lens Failure	<u>Inability to control focus, zoom, or iris.</u> <u>Worst Case:</u> <u>Loss of mission critical video.</u>	<p><u>Harrow Angle Zoom Lens Assembly</u></p> <p>The lens utilized in the HLA and CLA is a 18 mm to 108 mm Canon varifocal (200mm) lens with a minimum f-stop of 1.6 to T-120 and a fully closed position. By design the lens selected after much evaluation was a high quality commercially available unit procured to a Shuttle CCTV specification.</p> <p>The vendor item is specified to include only materials and lubricants which meet the RCA and STS approved lists; and final cleaning, assembly, and lubrication is completed in the USA plant under RCA field quality controls.</p> <p>The lens has been exposed to developmental testing and qualification testing as required for the STS cable and cargo bay environments.</p> <p>This assembly has been used on all STS developmental and operational missions.</p> <p><u>QUALIFICATION TEST</u></p> <p>For Qualification Test flow, see Table 2 located at the front of this book.</p>	
FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE						
Loss of Iris Function (Mechanical). Loss of Zoom Function (Mechanical). Loss of Focus Function (Mechanical). CLA - Motor Failure - Gear Train Failure - Lens Failure	<u>Inability to control focus, zoom, or iris.</u> <u>Worst Case:</u> <u>Loss of mission critical video.</u>	<p><u>Harrow Angle Zoom Lens Assembly</u></p> <p>The lens utilized in the HLA and CLA is a 18 mm to 108 mm Canon varifocal (200mm) lens with a minimum f-stop of 1.6 to T-120 and a fully closed position. By design the lens selected after much evaluation was a high quality commercially available unit procured to a Shuttle CCTV specification.</p> <p>The vendor item is specified to include only materials and lubricants which meet the RCA and STS approved lists; and final cleaning, assembly, and lubrication is completed in the USA plant under RCA field quality controls.</p> <p>The lens has been exposed to developmental testing and qualification testing as required for the STS cable and cargo bay environments.</p> <p>This assembly has been used on all STS developmental and operational missions.</p> <p><u>QUALIFICATION TEST</u></p> <p>For Qualification Test flow, see Table 2 located at the front of this book.</p>						

ITEM NO. <u>4.2.B.2</u>	SIMULIC CCTV CRITICAL ITEMS LIST	UNIT <u>TVC/CLA</u> ORG NO. <u>2294819-506_5082</u> SHEET <u>5</u> OF <u>11</u>
<p>CRITICALITY <u>2/2</u></p> <p>FAILURE MODE AND CAUSE</p> <p>Loss of Iris Function (Mechanical). Loss of Zoom Function (Mechanical). Loss of Focus Function (Mechanical).</p> <p>CLA</p> <ul style="list-style-type: none"> - Motor Failure - Gear Train Failure - Lens Failure 	<p>FAILURE EFFECT ON THE ITEM</p> <p>Inability to control focus, zoom, or iris.</p> <p><u>Worst Case:</u> Loss of mission critical video.</p>	<p>RATIONALE FOR ACCEPTANCE</p> <p>ACCEPTANCE TEST</p> <p>The CCTV systems' TVC/CLA is subjected directly, without vibration isolators which might be used in their normal installation, to the following testing:</p> <ul style="list-style-type: none"> * Vibration: 20-80Hz: 3 dB/Oct-rise from 0.01 G²/Hz 80-350 Hz: 0.04 G²/Hz 350-750 Hz: -3 dB/10 Oct-slope Test Duration: 1 Minute per Axis Test Level: 6.1 Grms * Thermal Vacuum: In a pressure of 1×10^{-5} Torr, the temperature shall be as follows: <ul style="list-style-type: none"> 125° F: Time to stabilize equipment plus 1 hour 25° F: Time to stabilize equipment plus 1 hour 125° F: Time to stabilize equipment plus 1 hour <p>The TVC/CLA may not have been subjected to the vacuum condition.</p> <p>For Acceptance Test Flow, see Table I located at the front of this book.</p> <p>OPERATIONAL TEST</p> <p>In order to verify that CCTV components are operational, a test must verify the health of all the command related components from the PHS (A7AII) panel switch, through the RCU, through the sync lines to the Camera/PIU, to the Camera/PIU command decoder. The test must also verify the camera's ability to produce video, the VSU's ability to route video, and the monitor's ability to display video. A similar test would be performed to verify the HUM command path.</p> <p>Pre-launch on Orbiter Test/In-Flight Test</p> <ol style="list-style-type: none"> 1. Power CCTV System. 2. Via the PHS panel, select a monitor as destination and the camera under test as source. 3. Send "Camera Power On" command from PHS panel. 4. Select "External Sync" on monitor. 5. Observe video displayed on monitor. Note that if video on monitor is synchronized (i.e., stable raster) then this indicates that the camera is receiving composite sync from the RCU and that the camera is producing synchronized video. 6. Send Pan, Tilt, Focus, Zoom, DTR, AND Gamma commands and visually (either via the monitor or direct observation) verify operation. 7. Select downlink as destination and camera under test as source. 8. Observe video routed to downlink. 9. Send "Camera Power Off" command via PHS panel. 10. Repeat Steps 5 through 9 except issue commands via the HUM command path. This proves that the CCTV equipment is operational.

FMEA NO. <u>4.2.6.2</u>		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT <u>TVC/CLB</u> DWG NO. <u>2294819-506, 508/</u> <u>2294821-503</u> SHEET <u>6</u> OF <u>11</u>
FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE	
<p>Loss of Iris Function (Mechanical), Loss of Zoom Function (Mechanical), Loss of Focus Function (Mechanical).</p> <p>CLB</p> <ul style="list-style-type: none"> - Motor Failure - Gear Train Failure - Lens Failure 	<p>Inability to control focus, zoom, or iris.</p> <p>Worst Case: Loss of mission critical video.</p>	<p><u>QA Inspection</u></p> <p>Procurement Control - The TVC/CLB EEE Parts and hardware items are procured from approved vendors and suppliers who meet the requirements set forth in the CCTV contract and Quality Plan Work Statement (HS-2593)761. Resident DCAS personnel review all procurement documents to establish the need for GSI on selected parts (PAI 517).</p> <p>Incoming Inspection and Storage - Incoming Quality inspections are made on all received materials and parts. Results are recorded by lot and retained in file by drawing and control numbers for future reference and traceability. All EEE parts are subjected to incoming acceptance tests as called for in PAI 315 - Incoming Inspection Test Instructions. Incoming flight parts are further processed in accordance with RGA 1846684 - Preconditioning and Acceptance Requirements for Electronic Parts, with the exception that DPA and PINO testing is not performed. Mechanical items are inspected per PAI 316 - Incoming Inspection Instructions for mechanical items, PAI 305 - Incoming Quality Control Inspection Instruction, and PAI 612 - Procedure for Processing Incoming or Purchased Parts Designated for Flight Use. Accepted items are delivered to Material Controlled Stores and retained under specified conditions until fabrication is required. Non-conforming materials are held for Material Review Board (MRB) disposition. (PAI-307, PAI IQC-531.)</p> <p><u>Board Assembly & test</u> - Prior to the start of CLB board assembly, all items are verified to be correct by stock room personnel, as the items are accumulated to form a kit. The items are verified again by the operator who assembles the kit by checking against the as-built-parts-list (ABPL). DCAS Mandatory Inspection Points are designated for all printed circuit, wire wrap and welded wire boards, plus harness connectors for soldering/wiring, crimping, solder splices and quality workmanship prior to coating of the component side of boards and sleeving of harnesses.</p> <p><u>CLB Boards</u></p> <p>Specific instructions are given in assembly drawing notes and applicable documents called out in the fabrication procedure and record (FPK-2307088) and Parts List PL 2307088. These include wire connection list 2295902, Notes - wide angle zoom lens assy 2303191, Process Standard - bonding staking, potting, encapsulating 2280478, Specification - Urethane protective coating 2280872 and Workmanship Spec 8010035.</p>	

FMEA NO. <u>4.2.6.2</u>	SUBTITLE CCIV CRITICAL ITEMS LIST	UNIT <u>TVC/CLA</u> DMG NO. <u>2294819-506, 508/</u> <u>2294821-503</u> SHEET <u>7</u> OF <u>11</u>
FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE
Loss of Iris Function (Mechanical). Loss of Zoom function (Mechanical). Loss of Focus Function (Mechanical). CLA - Motor Failure - Gear Train Failure - Lens Failure	Inability to control focus, zoom, or iris. Worst Case: Loss of mission critical video.	<p>QA INSPECTION (Continued)</p> <p>CLA Assembly and test - An open box test is performed per TP-IT-2294821, Acceptance Test per TP-AT-2294821. Torques are specified and witnessed, traceability numbers are recorded and calibrated tools are checked prior to use. RCA Quality and DCAS inspections are performed at the completion of specified FPR operations in accordance with PAI 204, PAI-205, PAI-217 and PAI-402. DCAS personnel witness RLA button-up and critical torquing.</p> <p>TVC/CLA - After a TVC/CLA have been tested individually, they are mated and a final acceptance test is performed per TP-AT-2294819, including vibration and thermal vacuum environments. RCA and DCAS personnel monitor these tests and review the acceptance test data/results. These personnel also inspect after all repair, rework and retest.</p> <p>Preparation for Shipment - The TVC and CLA are separated prior to shipment after fabrication and testing is complete. Each is packaged according to CCIV letter 8011 and 228074b, Process Standard for Packaging and Handling guidelines. All related documentation including assembly drawings, Parts List, ABPL, Test Data, etc., is gathered and held in a documentation folder assigned specifically to each assembly. This folder is retained for reference. An EIDP is prepared for each assembly in accordance with the requirements of WS-2593176. RCA QC and DCAS personnel witness rating, packaging, packing, and marking, and review the EIDP for completeness and accuracy.</p>

FMEA NO. <u>4.2.6.2</u>	CRITICALITY <u>2/2</u>	SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT <u>IVC/CLA</u> DWG NO. <u>2294019-506, 508/</u> <u>2294021-503</u> SHEET <u>8</u> OF <u>11</u>
FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE	
Loss of Iris Function (Mechanical). Loss of Zoom Function (Mechanical). Loss of Focus Function (Mechanical).	Inability to control focus, zoom, or iris. <u>Worst Case:</u> Loss of mission critical video.	<p>FAILURE HISTORY</p> <p>TDR V7663 Log #0221 CLA S/N002-501</p> <p><u>Description:</u> Acceptance Test Failure, Box level Ambient Environment. Focus drive appear to be intermittent at a particular point in travel of the lens barrel.</p> <p><u>Cause:</u> Low torque on stepper motor.</p> <p><u>Corrective Action:</u> Install Proto motor S/M 006. The motor which was removed can be used for the zoom or iris functions if it will pass the torque test; if not, return to vendor. Torque test per CCTV-0-31B. Early Motors had problems due to improper magnetization.</p> <p>TDR Y9298 Log #0228 CLA S/N F004-502</p> <p><u>Description:</u> Flight Failure Spacecraft Level. Focus hesitates at both ends of travel.</p> <p><u>Cause:</u> Tension spring of old design, 20 leaves.</p> <p><u>Corrective Action:</u> ECN CCT 1D10-C7762 changed 20 leaves to 15. Rework assembly with new spring.</p>	

FMEA NO. <u>4.2.6.2</u>		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT <u>TVC/CLA</u> DWG NO. <u>2294819-506</u> <u>5087</u> <u>2294821-503</u> SHEET <u>9</u> OF <u>11</u>
FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE	
Loss of Iris Function (Mechanical). Loss of Zoom Function (Mechanical). Loss of focus Function (Mechanical). SLB - Motor Failure - Gear Train Failure - Lens Failure	Inability to control focus, zoom, or iris. <u>Worst Case:</u> Loss of mission critical video.	<u>FAILURE HISTORY (Continued)</u> <u>TDR C6736 Log #2075 CLA S/N F001-503</u> <u>Description:</u> Field Test failure, Box Level, Ambient Environment. Lens does not focus over its complete range. NASA problem report PV6-038532. <u>Cause:</u> Lens sent to vendor for analysis for poor zoom. <u>Corrective Action:</u> Lens disassembled-re-cleaned. A new roller on zoom to permit a more stable zoom action. <u>TDR H2625 Log #0451 CLA S/N F001-502</u> <u>Description:</u> Acceptance Test failure, Box Level, Ambient Environment. Lens focus motor stalls when traveling from focus far to focus near. <u>Cause:</u> High torque in lens assembly; low torque in focus motor drive assembly. <u>Corrective Action:</u> Focus motor assembly torque increased. ECN ACCIV613 CPFB1253 issued for specification change for new torque requirements.	

FMEA NO.	4.2.6.2	SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT	SVC/CLA
CRITICALITY	2/2		DWG NO.	2294819-506, 508/ 2293821-503
FAILURE MODE AND CAUSE			SHEET	10 OF 11
Loss of Iris Function (Mechanical). Loss of Zoom Function (Mechanical). Loss of Focus Function (Mechanical).				
<u>CLA</u> - Motor Failure - Gear Train failure - Lens Failure	<u>FAILURE EFFECT ON END ITEM</u> Inability to control Focus, zoom, or iris. <u>Worst Case:</u> Loss of mission critical video.	<u>RAISONNALE FOR ACCEPTANCE</u>		
		<u>FAILURE HISTORY</u> (Continued)		
		1DR N0014 Log #0437 CLA S/N F001-502 <u>Description:</u> Acceptance Test failure, Box level. Vibration Environment. CLA lens assembly element loosened internally when vibrated with TVC S/N007. <u>Cause:</u> Improper staking method by manufacturer as required per specification 2295551. <u>Corrective Action:</u> All CLA lens assemblies returned to vendor for restaking of the front, rear and zoom elements.		
		1DR W4b76 Log #0522 CLA S/N F005-502 <u>Description:</u> Qualification Test Failure, Box Level, Thermal Vac-Cold Environment. Could not focus video presentation when tested with TVC F013/ <u>Cause:</u> Shaft in gear head assembly slipping. <u>Corrective Action:</u> Motor assembly replaced with new one. Motor returned to vendor where it was determined that the staking procedure was insufficient for proper operation. Manufacturer revised staking method for rework.		
		1DR V8593 Log #425 TVC S/N007 CLA S/N001-501 <u>Description:</u> Acceptance Test Failure, Box Level, Ambient Environment. Zoom lens hangs up during Pre-Vib test. <u>Cause:</u> Gear/shaft staking process insufficient to hold up under load without slipping. <u>Corrective Action:</u> Returned defective assembly to manufacturer for analysis & repair. Manufacturer revised staking procedure. Identified all units needing rework. ECR written to the RCA procurement specification (2291297).		

FMEA NO. <u>4.2.6.2</u>	SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT <u>TVC/CLA</u> DWG NO. <u>2204819-506, 508Z</u> <u>2294821-503</u> SHEET <u>11</u> OF <u>11</u>
FAILURE MODE AND CAUSE Loss of Iris Function (Mechanical). Loss of Zoom Function (Mechanical). Loss of Focus function (Mechanical). <u>CLA</u> - Motor Failure - Gear Train Failure - Lens Failure	FAILURE EFFECT ON END ITEM Inability to control focus, zoom, or iris. <u>Worst Case:</u> Loss of mission critical video.	RATIONALE FOR ACCEPTANCE <u>OPERATIONAL EFFECTS</u> Loss of video. Possible loss of major mission objectives due to loss of RHS cameras or other required cameras. <u>CREW ACTIONS</u> If possible, continue RHS operations using alternative visual cues. <u>CREW TRAINING</u> Crew should be trained to use possible alternatives to CCTV. <u>MISSION CONSTRAINT</u> Where possible, procedures should be designed so they can be accomplished without CCTV.