

CR  
LINE CRITICAL ITEM REPORT

Page: 1  
Date: 01/04/90

09/01/89 DATES DUE 06/02/89

ANALYST:

NAME	FAILURE	FAILURE EFFECT	RECOMMENDATION
PSS	MODE 2		
RTF	CAUSED		
ITEM NUMBER	ITEM		
ADAPTER ITEM 891	171	4910002; External gas leakage.	A. Design - Sealing surfaces on the 891 are 3006-16 aluminum coated with B7tuff and located on an inside diameter of the adapter body. The other part of this radial O-seal configuration, located on item 146, is protected from damage by the flange itself. The chamfered edges and edge breaks on the item 146 make damage to the adapter body sealing surface unlikely. and the restricted edge radius at the interface to the adapter body inside diameter makes the possibility of damage to the item 146 O-ring low. The radial (full moon) O-seal configuration and the four pin retention feature between the item 146 retainer valve and the 891 adapter body provide east seal squeeze under 810 tolerance conditions. The minimum seal squeeze for this configuration is 0.0093 in.
9799770-1			B. Test - PDA Test - Max PDA is external leak tested per 300U-5A-010 Para. 1.9. 25.0 cc/min at 0.01 in. Hg is obtained at P.0 = 0.04 psid.
Q1			Certification Test -
			D. Inspection - Both the O-seal and sealing surfaces on the item 146 and 891 are 100% inspected for dimension and surface finish requirements.
			E. Failure history - None.
			F. Around Environment - Tested for External leakage per 300U-5-003.

F. Operational Day -  
Crew Response -  
PRACTICE for other tests, cycle the Q2 actuator more  
frequently to attain test conditions. For greater tests,  
consider manual plugging of adapter valve and estimating the  
pressure achieved.

493  
PAGE 1 OF 2  
Change 3  
10/10/89

CTL  
EMU CRITICAL ITEMS LIST

Page: 2  
Date: 12/14/89

NAME	P/N	CRIT	FAILURE	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
		I/1	401PN024		Standard EMU training covers this failure mode. Operational Considerations - No constraints for single failure.