

CEL  
EMU CRITICAL ITEMS LIST

Page: 1  
Date: 12/06/93

12/24/93 SUPERSEDES 12/24/91

ANALYST:

NAME	FAILURE	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE																			
P/R	MODE 1																					
QTY	CRIT	CAUSES																				
RELIEF VALVE ITEM 493 SV792696-3 (1)	2/IR	493FH01: Fall closed.  CAUSE: Jawing, filter clogs, seat stiction.	END ITEM: Oxygen flow through valve poppet curtailed.  CIE INTERFACE: Unable to provide suit overpressure protection in the event of a failed open 113D regulator.  MISSION: None for single failure.  CREW/VEHICLES: None for single failure. Possible damage to suit if 113D or 113E regulator also fails open, or 492 gauge fails low. Possible loss of crewmans from decompression sickness.	A. Design - Jawing: The fit and wheelbase of the valve guides provides close concentricity control while allowing free pitch and alignment to seat the valve. With this geometry, jawing due to side loads is prevented while valve seating is maintained under all tolerance conditions. Clogged Filter: The filter screen area is made as large as possible (1.4 square inches) to prevent flow interruption except under severe contamination conditions. The valve is cleaned to, and maintained and tested in an environment of cleanliness, level EH150B per SVMS3150.  B. Test - Component Acceptance Test - The item is maximum flow tested by pressurizing the inlet to 8.30 psig and requiring the minimum flow to be 7.00 lba 02/hr.  PQA Test - A maximum flow test, identical to the test defined above is conducted during PQA per SEMU-60-016.  Certification Test - The BTA completed the following Certification Cycles in 9/90:  <table> <thead> <tr> <th>Test</th> <th>Actual Cycles</th> <th>Spec. Cycles</th> </tr> </thead> <tbody> <tr> <td>Proof Press. (13.3 psi)</td> <td>16</td> <td>16</td> </tr> <tr> <td>Crack/Max Flow</td> <td>2100</td> <td>2100</td> </tr> <tr> <td>Mate/Demate</td> <td>598</td> <td>500 Latch Seal</td> </tr> <tr> <td>Poppet Keeper Retraction</td> <td>312</td> <td>312</td> </tr> <tr> <td>Burst Pressure (32.2 psi)</td> <td>1</td> <td>1</td> </tr> </tbody> </table>	Test	Actual Cycles	Spec. Cycles	Proof Press. (13.3 psi)	16	16	Crack/Max Flow	2100	2100	Mate/Demate	598	500 Latch Seal	Poppet Keeper Retraction	312	312	Burst Pressure (32.2 psi)	1	1
Test	Actual Cycles	Spec. Cycles																				
Proof Press. (13.3 psi)	16	16																				
Crack/Max Flow	2100	2100																				
Mate/Demate	598	500 Latch Seal																				
Poppet Keeper Retraction	312	312																				
Burst Pressure (32.2 psi)	1	1																				

The BTA Assembly completed the 15-year random vibration (48  
minutes per axis), sinusoidal vibration, design and bench  
shock testing in 9/89.

C. Inspection -  
The spring and sliding surfaces of the poppet and housing  
are 100% inspected for dimensional and surface finish  
requirements. The parts are cleaned to level EH150B per  
H93150 prior to assembly.

CIL  
EMU CRITICAL ITEMS LIST

Page: 2  
Date: 12/06/93

12/24/93 SUPERSEDES 12/26/91

ANALYST:

NAME P/N QTY	FAILURE MODE & CRUSES	FAILURE EFFECT	NATIONALE FOR ACCEPTANCE
2/1R	493FHD1:		

D. Failure History -  
H-EMU-493-A002 (10-29-88)

During BTA certification testing, the suit pressure exceeded the 8.6 psig limit at the maximum flow condition. Failure caused by a greater than expected pressure drop (75%) across the 146 relief valve with poppet physically held open. EC 163402-265 issued to readjust the relief valve to reduce the BTA relief valve control pressure (inlet pressure) to outlet pressure from 8.6 psig to 8.45 psig.

H-EMU-493-A001 (10-20-88)  
The pressure drop across the valve was above specification limit during maximum flow testing due to relief valve "chattering" in the test rig configuration. The test rig utilizes an air line to feed the BTA while the actual BTA installation has a 146 valve upstream which acts as an upstream orifice to dampen frequency effects. Acceptance test for 491 was changed to include an upstream 146 (or equivalent) on the test rig.

H-EMU-493-A002 (5/15/89)  
The pressure drop across the valve was above specification limit during maximum flow testing because the valve was manufactured at the upper pressure limit with no margin for drift or test repeatability. EC163402-334 provides for an additional 0.15 PSI margin between the vendor's Acceptance Test requirements, 8.30 psig and 88 PDU requirement, 845 psig.

H-EMU-493-A003 (1/27/92) and H-EMU-493-A001 (2/14/92) - The BTA relief valve failed closed during Acceptance testing. The vendor's pressure gage was found to be incorrectly calibrated. The gage calibration vendor was changed to the gage manufacturer.

E. Ground Turnaround -  
Tested per FEMU-R-001. BTA relief valve checkout.

F. Operational Use -  
Crew Response -  
PostEVA: No response, single failure undetectable by crew or

CIL  
EMU CRITICAL ITEMS LIST

Page: 3  
Date: 12/06/95

12/24/93 SUPERBEDS 12/24/91

ANALYST:

NAME	FAILURE	MODE &	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
P/N	CRIT	CAUSES		
QTY				
2/1R	483PN012			ground. Training - Standard EMU training covers this mode. Operational Considerations - N/A