

FIL  
CHU CRITICAL ITEMS LIST

10/31/90 SUPERSEDES 06/31/90

Page 1  
Date 12/03/90

NAME P/N OFF	CR#1	FAILURE MODE & CAUSES	FAILURE EFFECT	ANALYSIS	
					RATIONALE FOR ACCEPTANCE
RELIEF VALVE STEM 491	170	493FM02; Faults open.	BURST; Built gas leakage to ambient through poppet seat.	A. Design - Spring failures: The valve loading spring stress at 94ksi is 90% below the torsional yield. Because of the very short (0.015 inch) valve stroke, the spring is not subjected to significant fatigue loading. These conditions result in a conservatively stressed spring.  BRE (INTERFACE); Inability to pressurize suit.	
S9702606-3 (1)		Crusher Spring failure, Jawing, contamination.	HESSLOW Loss of breath Treatment capability.	Jawings: The fit and clearances of the valve guide provide close concentricity control while allowing free pitch and alignment to seat the valve. With this geometry, jawing due to side loads is prevented, while valve seating is maintained under all service conditions. Contamination: An Inlet filter protects the valve from particles greater than .006" in size. The valve seal, consisting of a sharp lip contacting an elastomeric seal, can accept tiny particles and maintain a seal.	

ORIV/VEHICLE;  
Possible loss of  
crayon from  
decompression  
stitchless.

B. Test -  
Component Acceptance Test -  
The item is external leakage tested per vendor test sheets  
to 7.0-8.0 psig where a maximum leakage of 25.0 cc/min O<sub>2</sub>  
is allowed. The item is also pressure tested, then reseal  
tested. Reseat must occur by 7.0 psig minimum.

PSI Test -  
Both an external leakage, and reseat test, identical to the  
tests defined above, are conducted during PDI per  
1ENR-40-016 except maximum allowed external leakage is 35.0  
cc/min O<sub>2</sub>.

Certification Test -  
The DIA completed the following Certification Cycles in  
9/90:

Test	Actual Cycles	Spec. Cycles
Proof Press. (13.3 psi)	16	16
Crack/Max flow	2100	2100
Rate Damage	500 Latch Seal	500 Latch Seal
Poppet Keeper Retraction	312	312
Burst Press. (32.0 psi)	1	1

The DIA Assembly completed the 10-year random vibration (40  
minutes per axis), sinusoidal vibration, design and bench  
shock testing in 9/90.

CIE  
EMD CRITICAL ITEMS LIST

10/31/79 SUPERSEDES 08/31/79

Page 2  
Date: 12/03/80

NAME	FAILURE	ANALYSIS
P/N	MODE L	
QTY	CRASH	
1/1	4950H022	

FAILURE EFFECT      RATIONALE FOR ACCEPTANCE

**G. Inspection -**  
The spring and sliding surfaces of the poppet and housing are 100% Inspected for dimensional and surface finish requirements. The parts are cleaned to level EM1301 SWH3350 prior to assembly.

**H. Failure History -**  
B-TMU-4PS-C001 (11-30-87) - The relief valve leaked over specification due to contamination preventing the poppet from fully sealing on the valve body seat. As a result, a filter was installed in the vendor test rig immediately upstream of the item.

**I. Ground Turnaround -**  
Tested per EMU-R-001, STA relief valve checkout.

**F. Operational Use -**  
**Crew Response -**  
Handle sheet problem. Consider RM to close relief valve and use helium purge valve to control melt pressure.  
**Training -** Standard IMA training covers this failure mode.  
**Operational Considerations -**  
Not applicable.

SP-EMU-4PS-C001  
Page 1843  
Change 2