

E&I
Critical Item Test

CRANE	FAILURE MODE & CAUSES	FAILURE EFFECT
SH-00 110159- 120200-01 Ultra 3.0 20kg	SC-0002 Physical jacking or locking of knob. CAUSES: Contamination or foreign material between knob and upper housing or around captive screw. Broken ratchet or ratchet teeth. Loose housing screws, thermal expansion.	IND. FILE: Unable to lock knob. GFE INFERENCES: Unable to loosen latch bolts. MISSION: Unable to jettison payload. Terminate EVA. CRAFT/VEHICLE: Loss of crew & vehicle.

Assembly Name/Part Number: Torque Multiplier/1055-20-19-01
 References: GRI-10001
 Prepared By: C. Harlan Approved By: R. Wilhoy
 Superseding Date: 9/28 Date: 1/89 Rev: A

RATIONALE FOR ACCEPTANCE

A. DESIGN:

Tight tolerances and close fit between knob and upper housing, ring seat and captive screw reduces the possibility of foreign material entering the knob assembly. The torque multiplier has a 9C level cleanliness requirement during both the assembly and acceptance operations which is further protection from contamination.

The knob Ratchet is fabricated from Custom 453, Condition A, heat treated to H1808 per MIL-H-8828 and passivated per QQ-P-35 specifications. The Ratchet teeth are fabricated from 15-5 PH stainless steel and heat treated in H1075 condition. They are also passivated per QQ-P-35 specifications. High strength materials and heat treated conditions preclude shear and breakage.

The possibility of loose housing screws in the torque multiplier assembly is precluded in design by adherence to standard engineering torque requirements for screw installation and the use of thread locking adhesive. The housing screws are installed using Loctite 1242, and its strength, and torqued to 25 in/lbs to assure that they remain in place.

The shelf life of Loctite is carefully monitored to eliminate unacceptable deterioration.

SH0210W
ATTACHMENT *
Page 127 of 151

Page B4-5 of B4-11
Release Date _____

5.0
Critical Items List

NAME	FAILURE	CAUSES	FAILURE EFFECT
IFRM	ROBE &		
IFRM	CAUSES		
IFRM	5.0.0.002		
IFRM	Physical		
IFRM	jamming or		
IFRM	binding of		
IFRM	Robe.		

Assembly Name/Part Number: Torque Multiplier/10109-20059-01
 Reference: EIL-89001
 Prepared By: C. Hartman Approved By: R. Willey
 Superceding Date: 7/00 Date: 7/09 Rev: A

RATIONALE FOR ACCEPTANCE

B. TESTS:
 Equipment Acceptance Test -
 None

PQA Test -
 The following tests are conducted at the
 Torque Multiplier Assembly level in accordance
 with ILC Document 10107-204901.
 b. Functional test to verify proper
 operation of Robe.

Certification Test -
 The torque multiplier was tested by 5/00
 requirements of eight cycles and exhibited no evidence
 of damage. It was certified for the worst case PQA Storage
 temperature range of -200 degrees F to +350 degrees F.

C. INSPECTION:
 Components and material manufactured to ILC
 requirements of an approved supplier are
 documented from procurement through shipping
 by the supplier. ILC incoming receiving
 inspection verifies that the materials
 received are as identified in the procurement
 documents, that no damage has occurred during
 shipment and that supplier certification has
 been received which provides traceability
 information.

SA02108
 ATTACHMENT -
 Page 128 of 153

Document No. 10107-70214
 Release Date
 Page 54-6 of 84-11

EII
Critical Items List

ITEM	FAILURE	CAUSES	FAILURE EFFECT
100005	NONE	NONE	
100006	None	Physical Jawing or binding of knob.	
100007	None		
100008	None		
100009	None		
100010	None		
100011	None		
100012	None		

Assembly Number/Part Number: Torque Multiplier /10150-20359-01
 Reference: EII 100007
 Prepared By: C. Hartage Approved by: R. Willey
 Superseding Date: 9/88 Date: 11/87 Rev: A

RADIOPHASE FOR ACCEPTANCE

The following RPP's are performed during the Torque Multiplier Assembly manufacturing process to assure the failure causes are precluded from the fabricated item:

1. Inspection of all components for damage or material degradation.
2. The issuance of Loctite is controlled by inspection.
3. Verification that Loctite shelf life is within specification.
4. Wellness of Loctite application and torque of captive screw.
5. Verification of cleanliness to NC level.
6. Verification of proper lubrication.

During PQA, the following inspection points are performed at the Torque Multiplier Assembly level in accordance with ITC Document 10307-74396.

1. Inspection to drawing and documentation.
2. Inspection for damage or material degradation.
3. Verification of successful completion of functional test.
4. Verification of cleanliness to NC level.

B. FAILURE HISTORY

None

SECTION
ATTACHMENT
Page 129 of 153

PAGE 84-7 OF 84-31

Release Date

Document No. 10107-70714

CN
Critical Items List

ITEM	FAILURE	CAUSES	FAILURE EFFECT
100159	NONE	None	
100299	NONE	None	
100300	NONE	None	
100301	NONE	None	

Assembly Name/Part Number: Torque Multiplier/TM-20059-A1
Reference: (IL IRDNCL)
Prepared By: D. Hartman Approved By: R. Wilkey
Superseding Date: 9/00 Date: 1/07 Rev: A

RATIONALE FOR RELIABILITY

E. GROUND TURNAROUND:

During ground turnaround, in accordance with ILC Document 10107-70713, the Torque Multiplier Assembly is disassembled, cleaned, re-lubricated, reassembled and tested for proper operation. It is then cleaned to VE level.

F. OPERATIONAL USE:

1. Crew Response
Pre/Post EVB - R/A
EVA - Transport Torque Multiplier to crew compartment, disassemble and clean.
(Requires additional EVB.)

2. Training
Crew Briefing.

3. Operational Considerations
Catastrophic failure. Possible loss of crew/vehicle.

SH0210W
ATTACHMENT -
Page 130 of 153