

Grumman Corporation

CRITICAL ITEMS LIST

GRUMMAN

ASSEMBLY Nomenclature: MANIPULATOR FOOT RESTRAINT
 ASSEMBLY PART NO: REF 3040100

PREPARED BY: L. HANN & F. PERAZZO

REPORT NO: PMS 07-5-8
 REVISION A
 DATE: 17 MAY 1988

FMEA REF	NAME, CITY & DRAWING REF DESIGNATION	CRIT	FAILURE MODE AND CAUSE	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
02 A	Vertical Stanchion Horizontal Indexing Mechanism QTY (1) Dwg C05-116-1	2/2	Q2 - Latch jammed in notch of Indexing mechanism due to contamination or gall- ing ; latch cannot be withdrawn from detent notch due to breaking of release cable	<u>END ITEM</u> Stanchion cannot be rotated. If failure occurs in position other than aligned with stow latch, vertical stanchion cannot be stowed. <u>GEE INTERFACE</u> None, since MFR will be jettisoned	<u>A. Design</u> Materials per tables 1 & 2 of MSFC-SPEC-522A are certified for traceability/quality. Anodic hardcoating per mil-A-8625C on aluminum interfaces with relative motion minimizes galling and wear. Contamination caused by corrosion by-products eliminated by extensive use of thermal control coating and solid (Moly di-sulfide) lubricant coating. Release cable worst case loads are extremely small compared to the ultimate strength of the cable which is sized for ease of manufacture and for resistance to handling damage.

Grumman Corporation

CRITICAL ITEMS LIST

PREPARED BY: L. HAHN & F. PERAZZO

ASSY Nomenclature: MANIPULATOR FOOT RESTRAINT
ASSEMBLY PART NO: NED 30403-100REPORT NO: PMS AF R II
REVISION: A/B
DATE: 6 JULY 1988

GRUMMAN

FMEA REF	NAME, QTY & DRAWING REF DESIGNATION	CRT	FAILURE MODE AND CAUSE	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
D2 A	Vertical Stanchion Horizontal Indexing Mechanism QTY (1) Dwg C35-1M-1	2/2	D2 - Latch jammed in notch of indexing mechanism due to contamination or gall- ing; latch cannot be withdrawn from detent notch due to breaking of release cable	<p>END ITEM Stanchion cannot be rotated. If failure occurs in position other than aligned with stow latch, vertical stanchion cannot be stowed.</p> <p>GFE INTERFACE None, since MFR will be jettisoned</p> <p>MISSION Loss of MFR; unable to accomplish subsequent mission objectives</p> <p>CREW / VEHICLE None</p>	<p>D. TEST HISTORY</p> <ol style="list-style-type: none"> Acceptance test per procedure 300-84-04 at Grumman [2/7/83] before and after witness. ATP includes functional tests of all operating functions and a general visual inspection. Stiffness test per procedure 300-301-04 at Grumman [7/7/83]. Demonstrated stanchion end play less than .5 inch for 64 pound load in any direction and deflection less than 3 inches lateral and 7 inches longitudinal for 1 hundred pound loads. Vibration and shock test per procedure 300-16-01 at Grumman [7/7/83]. Demonstrated ability to withstand design levels without structural failure with no significant resonance. Several screws required the application of torque. A/PCM/MF ultimate load tests per STS-03-094-1 at Rockwell [9/83]. Loads applied in 14 steps, each comprising 10% of limit load no yield was observed at the ultimate load of 1.4 x limit. Thermal vacuum test at JSC [02/84]. MFR was operated at ambient temperature, plus 22.0 and -127.0 (average lowest achievable chamber temp) at an average vacuum of .00006 torr. Center of gravity test at JSC [12/84] Moment of inertia swing test at JSC [V/85] <p>E. INSPECTION</p> <ol style="list-style-type: none"> NAYPRO inspects all production end items at completion of final assembly Anodic hard coated aluminum parts inspected for compliance to MIL-A-8625 C by DCA. Certificate of compliance on file at Grumman Birthpage. Thermal Control Coating process is controlled by inspections (post prime, cure, post coating and cure), and sample testing for coating thickness, coating adhesion, and enhance/solve absorption. <p>F. FAILURE HISTORY</p> <p>None (per PRACA database). The MFR has been successfully utilized on five missions, STS 11, 13, 51A, 51L, and 61C.</p> <p>G. TURNAROUND</p> <p>Inspection per 520/P/A-05001/N/C 10 DEC 1987 includes a function test of all MFR operating functions and a general visual inspection.</p> <p>H. OPERATIONAL USE</p> <ol style="list-style-type: none"> Operational Effect of Failure: MFR could not be restored. It possibly could not be used on a second EVA if it had to be jettisoned. MFR could still be used for EVA but it might increase the length of the EVA. Crew Action: none Crew Training: none Mission Constraints: none In Flight Checkout: Critical visually verify stanchion operation at time of use.