

CRITICAL ITEMS LIST

REFERENCE DESIGNATOR: HST-PFR-1
 NAME / QUANTITY: Pivot and Roll Assembly
 DRAWING REFERENCE: 4177100 & 4177101

PROJECT: HST
 LRU NAME / QUANTITY: PFRQ
 LRU PART NUMBER: 36000-0003-001

PAGE 1 OF 5
 SUBSYSTEM: PMA
 EFFECTIVITY: ALL ORBITERS

FAILURE MODE NUMBER HST-PFR-1-4	CRITICALITY 1R/2	FAILURE EFFECT	RETENTION RATIONALE
FUNCTION		END ITEM PFR loses stability, cannot be used	<ul style="list-style-type: none"> I. Design Feature to Minimize the Chance of the Failure Mode <p>A. Design All HST PFRs were designed to an ultimate structural safety factor of 1.4.</p>
FAILURE MODE AND CAUSE		MISISON Possible damage to the HST and/or primary servicing mission hardware	<p>B. Tolerances Sufficient tolerances were used in the HST PFR design to prevent jamming by expansion and contraction of material due to temperature extremes or on-orbit use.</p> <p>C. Materials - Major Components See material list (Table B-2).</p>
MODE While attached to an STS-PFR socket in the orbiter payload bay, the pivot and/or roll joint assembly inadvertently becomes unlocked and rotated when the crew member is in the HST PFR. CAUSES	<p>1) Torsion spring comes loose 2) Linkage comes loose</p>	CREW / VEHICLE Possible damage to orbiter	<p>D. Testing and Analysis</p> <ul style="list-style-type: none"> A. Acceptance Testing 1. PIA A full pre-installation acceptance (PIA) test will be performed on each HST PFR before it is delivered to KSC to support any STS flight. The PIA will verify that the HST PFRs are functioning within tolerances and that the assembly is clean. 2. Vibration The HST PFRs were exposed to qualification level vibration loads during their initial development in support of STS-31. The test verified that the HST PFRs were free of manufacturing defects and tolerance problems. (Reference LMSC Document number H177007-501.)
REDUNDANCY SCREENING	REPAIRING PATHS		
A - Pass B - Pass C - Pass	1 Crew is inhibited preventing the crew from boarding off.		
MISSION PHASE	CORRECTIVE ACTION TIMES		
	TIME TO EFFECT	TIME TO CORRECT	
EVA	Minutes	Seconds	HST

CRITICAL ITEMS LIST

REFERENCE DESIGNATOR: HST-PFR-1

NAME / QUANTITY: Pivot and Roll Assembly

DRAWING REFERENCE: 4177100 & 4177108

PROJECT

HST

LRU NAME / QUANTITY: PFR-1

LRU PART NUMBER: SED03H7963-001

TABLE 2 OF 5

SUBSYSTEM: HVA

EFFECTIVITY: ALL ORBITERS

FAILURE MODE NUMBER HST-PFR-1-4	CRITICALITY 1R2	FAILURE EFFECT	RETENTION RATIONALE																										
FUNCTION		END ITEM PFR loses stability, cannot be used																											
The pivot and roll joint allows the user to configure the PFR to a desired position by changing the elevation of the arm with respect to the PFR socket and rotating the PFR about the arm axis.		A. Acceptance Testing (continued) The following vibration levels are per: <table> <thead> <tr> <th>Frequency (Hz)</th> <th>Slope (dB/oct.)</th> <th>Constant Level (G²/Hz)</th> <th>Overall Gmax</th> </tr> </thead> <tbody> <tr> <td>20</td> <td></td> <td></td> <td>7.7</td> </tr> <tr> <td>20-45</td> <td>+7.0</td> <td>.009</td> <td></td> </tr> <tr> <td>45-600</td> <td></td> <td>.08</td> <td></td> </tr> <tr> <td>600-2000</td> <td>-6.0</td> <td></td> <td></td> </tr> <tr> <td>2000</td> <td></td> <td>.0054</td> <td></td> </tr> </tbody> </table>				Frequency (Hz)	Slope (dB/oct.)	Constant Level (G ² /Hz)	Overall Gmax	20			7.7	20-45	+7.0	.009		45-600		.08		600-2000	-6.0			2000		.0054	
Frequency (Hz)	Slope (dB/oct.)	Constant Level (G ² /Hz)	Overall Gmax																										
20			7.7																										
20-45	+7.0	.009																											
45-600		.08																											
600-2000	-6.0																												
2000		.0054																											
FAILURE MODE AND CAUSE		MISSION No effect on mission objectives if failure occurs in payload bay																											
MODE While attached to an STS-PFR socket in the orbiter payload bay, the pivot and/or roll joint assembly inadvertently becomes unlocked and rotates when the crew member is in the HST PFR. CAUSES/ES 1) Torsion spring comes loose 2) Linkage comes loose		CREW / VEHICLE Possible damage to orbiter																											
REDUNDANCY SCREENS		INTERFACE None																											
REMAINING PATHS A - Pass B - Pass C - Pass		1.) Crew is tethered preventing the crew from floating off.																											
MISSION PHASE		CORRECTIVE ACTION TIMES																											
		TIME TO EFFECT		TIME TO CORRECT																									
EVA		Minutes		Seconds																									

CRITICAL ITEMS LIST

REFERENCE DESIGNATION: HST-PFR-1
 NAME / QUANTITY: Pivot and Roll Assembly each
 DRAWING REFERENCE: 4177100 & 4177101

PROJECT: HST
 LRU NAME / QUANTITY: PFR/2
 LRU PART NUMBER: 9ED49107655-301

PAGE 3 OF 5
 SUBSYSTEM: N/A
 EFFECTIVITY: ALL ORBITERS

FAILURE MODE NUMBER HST-PFR-1-4	CRITICALITY 1R/2	FAILURE EFFECT	RETENTION RATIONALE
FUNCTION			
The pivot and roll joint allows the user to configure the PFR to a desired position by changing the elevation of the arm with respect to the PFR socket and rotating the PFR about the arm axis.			
FAILURE MODE AND CAUSE			
MODE While attached to an STS-PFR socket in the orbiter payload bay, the pivot and/or roll joint assembly inadvertently becomes unlocked and rotates when the crew member is in the HST PFR.		END ITEM PFR loses stability, cannot be used	C. <u>Certification Analysis</u> All HST PFR components were analyzed to the following induced environments to verify that the assembly can withstand the environment levels: I. Requirements Source II. Shock - Functional NSTS-07700 VOL. XIV - Acoustic NSTS-07700 VOL. XIV III. Vibration (Fit. Levels) - Acoustic NSTS-07700 VOL. XIV IV. Structures - Ult. ($f_s = 2.0$) NSTS-07700 VOL. XIV - Fracture NSTS-07700 VOL. XIV V. Acceleration - Flight MIL-STD-810, Meth. 518, Proced. I - Crash MIL0004-014D VI. Temperature - Hot (+250°F) NSTS-07700 VOL. XIV, Appendix 7 - Cold (-90°F) JSC-23560
CAUSE(S) 1) Tension spring comes loose 2) Linkage comes loose		MISSION No effect on mission objectives if failure occurs in payload bay	
REDUNDANCY SCREENING		CREW / VEHICLE Possible damage to orbiter	
A - N/A			
B - N/A			
C - N/A			
MISSION PHASE		CORRECTIVE ACTION TIMES	
		TIME TO EFFECT	TIME TO CORRECT
EVA	Minutes	N/A	
INTERFACE None			

CRITICAL ITEMS LIST

REFERENCE DESIGNATOR: HST-PFR-1
 NAME / QUANTITY: Pivot and Roll Joint/1 each
 DRAWING REFERENCE: 457100 & 457101

PROJECT: HST
 LRU NAME / QUANTITY: PFR/2
 LRU PART NUMBER: 94030107003-001

PAGE 4 OF 5
 SUBSYSTEM: N/A
 EFFECTIVITY: ALL ORBITERS

FAILURE MODE NUMBER HST-PFR-1-4	CRITICALITY 1R/2	FAILURE EFFECT	RETENTION RATIONALE
FUNCTION The pivot and roll joint allows the user to configure the PFR to a desired position by changing the elevation of the arm with respect to the PFR socket and rotating the PFR about the arm axis.		END ITEM PFR loses stability, cannot be used	III. Inspection A. Manufacturing: 1. The HST PFR components were inspected prior to build-up for conformance to their applicable drawings. B. Assembly: 1. All fracture critical piece parts were and will be inspected as described on their applicable drawings. C. Testing: 1. HST PFR will be cleaned and inspected to the levels described in JSC 5322B. Once cleaned, the HST PFR will be bagged to prevent any contamination from entering the unit.
FAILURE MODE AND CAUSE MODE While attached to an STS-PFR socket in the orbiter payload bay, the pivot and/or roll joint assembly inadvertently becomes unlocked and rotates when the crew member is in the HST PFR. CAUSE(S) 1) Torsion spring comes loose 2) Linkage comes loose		MISSION No effect on mission objectives if failure occurs in payload bay	
REDUNDANCY SCREENS A - N/A B - N/A C - N/A	ASSUMING PATH 1) Crew is tethered preventing the crew from floating off	CREW / VEHICLE Possible damage to orbiter	
MISSION PHASE	CORRECTIVE ACTION TIMES		
EVA	TIME TO EFFECT: Minutes	TIME TO CORRECT: N/A	

CRITICAL ITEMS LIST

REFERENCE DESIGNATION: HST-PFR-1

NAME / QUANTITY

Pivot and Roll Assembly

DRAWING REFERENCE

1077100 & 4177101

PROJECT: HST

LIU NAME / QUANTITY: PFR2

LIU PART NUMBER: 5ED34904003-204

PAGE 4 OF 5

SUBSYSTEM: N/A

EFFECTIVITY: ALL ORBITERS

FAILURE MODE NUMBER HST-PFR-1-4	CRITICALITY 1R2	FAILURE EFFECT	RETENTION RATIONALE
FUNCTION			
The pivot and roll joint allows the user to configure the PFR to a desired position by changing the elevation of the arm with respect to the PFR socket and rotating the PFR about the arm axis.			
FAILURE MODE AND CAUSE			
MODE While attached to an STS-PFR socket in the orbiter payload bay, the pivot and/or roll joint assembly inadvertently becomes unlocked and rotates when the crew member is in the HST PFR. CAUSES: 1) Torsion spring comes loose 2) Linkage comes loose		END ITEM PFR loses stability, cannot be used	IV. Failure History A. None. HST PFR flew on STS-31, but was not used during the mission.
		MISSION No effect on mission objectives if failure occurs in payload bay	V. Operations A. <u>Effects of Failure</u> Loss of stability, Possible damage to orbiter. B. <u>Crew Actions</u> Functionally check-out all joints after unstrapping from stowage location. C. <u>Training</u> Crew must be tethered during operation in the HST PFR. D. <u>Mission Constraints</u> None
		CREW / VEHICLE Possible damage to orbiter	E. In-Flight Check-Outs None
REDUNDANCY SCREENS		REMAINING PATHS	
A - N/A	B - N/A	1) Crew is tethered preventing the crew from floating off	
MISSION PHASE		CORRECTIVE ACTION TIMES	
		TIME TO EFFECT	TIME TO CORRECT
EVA		Minute	N/A
INTERFACE			
None			