

## CRF ITEMS LIST

PAGE 1 OF 5

SUBSYSTEM TOOL BOX  
EFFECTIVITY ALL ORBITERSREFERENCE DESIGNATOR: TBA-2  
NAME / QUANTITY: BACK-UP PANEL ASSY. (2)  
DRAWING REFERENCE: 1R181-202072028MPROJECT: HST  
LRU NAME / QUANTITY: BACK-UP PANEL ASSY. (2)  
LRU PART NUMBER: 0101-29207-01/29208-01

FAILURE MODE NUMBER HST-TBA-3-1	CRITICALITY 1R/2	FAILURE EFFECT	RETENTION RATIONALE
<b>FUNCTION</b>		<b>END ITEM</b> Cannot restore the back-up panels which prevents the lap panel from being closed and the doors from being shut.	<b>DESIGN</b> I. <u>Design Feature to Minimize the Chance of the Failure Mode</u> A. <u>Design</u> All tool box components were designed to a structural safety factor of 2.0.  B. <u>Tolerances</u> Sufficient tolerances will be used in the latch design to prevent jamming by expansion and contraction of material due to temperature extremes or on-orbit use.  C. <u>Materials - Major Components</u> 1. Latch Assembly: 6061-T651, CRES 304 Cond. A, 15-5PH 1025 2. Back-Up Panel Slide: CRES 304 Cond. A, Acetal, 5081-T651 3. Box Bottom and Top Panels: 7075-T73551
<b>FAILURE MODE AND CAUSE</b> <u>MODE</u>		<b>MISSION</b> Mission objectives are complete.	<b>II. Testing and Analysis</b> A. <u>Acceptance Testing</u> 1. PDA  A full pre-delivery acceptance (PDA) test will be performed on the tool box assembly before it is delivered to JSC for the beginning of the certification process. The PDA will verify that the latches are operating correctly and that the assembly is clean.
<b>CAUSE(S)</b> 1.) Latches are jammed closed. 2.) Contamination.		<b>CREW / VEHICLE</b> Possible damage to the orbiter if the doors or any content in the box become loose in the payload bay.	2. <u>Vibration</u>  The flight tool box will be exposed to acceptance vibration loads while it is in flight configuration. The test will verify that the latches will withstand the vibration loads.
RELIABILITY SCREENS	REMAINING PATHS	INTERFACE	
A - Pass B - N/A C - Pass	1) Release 5/16" hex-head bolts at hinge.	None	
MISSION PHASE	<b>CORRECTIVE ACTION TIMES</b>		
	TIME TO EFFECT	TIME TO CORRECT	
EVA	Hours	Minutes	

PREPARED BY: J. F. PARK

REVISION: BASIC

SUPERSEDED DATE: NONE

DATE: 01/08/02

HST-TBA-1-19

## CRIT ITEMS LIST

PAGE 2 OF 6

SUBSYSTEM: TOOL BOX  
EFFECTIVITY: ALL ORBITERSREFERENCE DESIGNATOR: TBA-2  
NAME / QUANTITY: BACK-UP PANEL ASSY. (2)  
DRAWING REFERENCE: 19991-20007/2000PROJECT: HST  
LRU NAME / QUANTITY: BACK-UP PANEL ASSY. (2)  
LRU PART NUMBER: 10161-20287-01/2000-01

FAILURE MODE NUMBER HST-TBA-3-1	CRITICALITY 1R/2	FAILURE EFFECT	RETENTION RATIONALE				
<b>FUNCTION</b>		<b>END ITEM</b>  Cannot restore the back-up panels which prevents the lap panel from being closed and the doors from being shut.	<b>DESIGN</b>  A. Acceptance Testing (continued)				
The back-up panels are used to store the back-up tools within the tool box.			The following vibration levels are per SMD memo ES42-92-134:				
<b>FAILURE MODE AND CAUSE</b>			Frequency (Hz)	Slope (dB/oct.)	Constant Level G <sup>2</sup> /Hz	Overall G rms	
<b>MODE</b>  Either back-up panel is stuck in the deployed position.			20-80	+3.0	.04	6.1	
<b>CAUSE(S)</b>  1.) Latches are jammed closed. 2.) Contamination.		<b>MISSION</b>  Mission objectives are complete.	80-350	-3.0			
			350-2000	-3.0			
			20-45	+10.0	.08	7.7	
			45-800	-4.0			
			800-2000	-6.0			
			20-70	+4.0	.05	7.0	
			70-600	-4.0			
			600-2000	-6.0			
			<b>B. Qualification Testing</b>				
			1. Thermal Vacuum				
			The Tool Box will be exposed to the following thermal vacuum environment. Latch operation and contingency bolts operation will be a part of the test plan.				
			a. Temperature - Cold Side Only (amb. to -90°F)				
			b. Pressure - ATM to 1x10 <sup>-5</sup> torr				
REdundancy SCREENS	REMAINING PATHS						
A - Pass	1) Release 5/16" hex-head bolts at hinge.						
B - N/A							
C - Pass							
<b>MISSION PHASE</b>	<b>CORRECTIVE ACTION TIMES</b>						
TIME TO EFFECT	TIME TO CORRECT						
EVA	Hours	Minutes					

REVISION: BASIC

SUPERSEDED DATE: NONE

DATE: 07/02

PREPARED BY: J.F. PARK

HST-TBA-1-20

## CRI ITEMS LIST

PAGE 3 OF 5

REFERENCE DESIGNATOR: TBA-2  
 NAME / QUANTITY: BACK-UP PANEL ASSY. (2)  
 DRAWING REFERENCE: 10181-00207-01/2000-07

PROJECT: HST  
 LRU NAME / QUANTITY: BACK-UP PANEL ASSY. (2)  
 LRU PART NUMBER: 10181-00207-01/2000-07

SUBSYSTEM: TOOL BOX  
 EFFECTIVITY: ALL ORBITERS

FAILURE MODE NUMBER HST-TBA-3-1	CRITICALITY 1R/2	FAILURE EFFECT	RETENTION RATIONALE
<b>FUNCTION</b>		<b>END-ITEM</b> Cannot restow the back-up panels which prevents the lap panel from being closed and the doors from being shut.	<b>DESIGN</b> B. Certification Testing (continued)
The back-up panels are used to store the back-up tools within the tool box.			2. Functionals  The tool box components like the door panel latches will be functionally operated prior to and immediately after all certification test to verify that the test environment does not degrade the hardware performance.
<b>FAILURE MODE AND CAUSE</b>		<b>MISSION</b> Mission objectives are complete.	C. Certification Analysis The door panel latches and hinges will be analyzed to the following induced environments to verify that the assembly can withstand the environment levels:
<b>MODE</b> Either back-up panel is stuck in the deployed position.  <b>CAUSES:</b> 1.) Latches are jammed closed. 2.) Contamination.		<b>CREW / VEHICLE</b> Possible damage to the orbiter if the doors or any content in the box become loose in the payload bay.	1. Requirements      Source  a. <u>Shock</u> - Functional      NSTS-07700 VOL. XIV  b. <u>Vibration (Ft. Levels)</u> - Acoustics      NSTS-07700 VOL. XIV - Modal      JSC-14046  c. <u>Structures</u> - Ult. (Is = 2.0)      NSTS-07700 VOL. XIV - Fracture      NSTS-07700 VOL. XIV  d. <u>Acceleration</u> - Flight      MF0004-014D - Crash      MIL-STD-810, Method 516, Procedure I  e. <u>Temperature</u> - Hot (+250°F)      HST S/AD (10181-10081A)
RELIABILITY SCORES	REMAINING PATHS		
A - Pass B - N/A C - Pass	1) Release 5/16" hex-head bolts at hinge.		
MISSION PHASE	<b>CORRECTIVE ACTION TIMES</b>		
	TIME TO EFFECT	TIME TO CORRECT	
EVA	Hours	Minutes	

PREPARED BY: J. F. PARK

REVISION: BASIC

SUPERSEDED DATE: NONE

DATE: 07/00

## C AL ITEMS LIST

PAGE 4 OF 5

REFERENCE DESIGNATOR: TBA-2  
NAME / QUANTITY: BACK-UP PANEL ASST. (2)  
DRAWING REFERENCE: 10181-20207/20208

PROJECT: HST  
LRU NAME / QUANTITY: BACK-UP PANEL ASST. (2)  
LRU PART NUMBER: 10181-20207-01/20208-01

SUBSYSTEM: TOOL BOX  
EFFECTIVITY: ALL ORBITERS

FAILURE MODE NUMBER HST-TBA-3-1		CRITICALITY 1R/2	FAILURE EFFECT	RETENTION RATIONALE
<b>FUNCTION</b>			<b>END ITEM</b> Cannot stow the back-up panels which prevents the lap panel from being closed and the doors from being shut.	<b>DESIGN</b> <b>III. Inspection</b> <b>A. Manufacturing</b> 1. The latches and door panel hinge components will be inspected prior to build-up for conformance to their applicable drawings. 2. All fracture critical piece parts will be inspected as described on their applicable drawings. <b>B. Assembly</b> 1. Interior assemblies will be cleaned and inspected to the levels described in section 3.53.5 of the HST S/AD (10181-10081-01). Once cleaned, the tool box will be completely bagged to prevent any contamination from entering the box. <b>C. Testing</b> 1. The assembly will be fully inspected and functionally operated during PDAs and PIAs. 2. The hardware will be fully inspected for any signs of galling as a part of the pre/post functional tests performed prior to and immediately after all major certification and acceptance testing.
<b>FAILURE MODE AND CAUSE</b> <b>MODE</b> Either back-up panel is stuck in the deployed position. <b>CAUSES</b> 1) Latches are jammed closed. 2) Contamination.			<b>MISSION</b> Mission objectives are complete.  <b>CREW / VEHICLE</b> Possible damage to the orbiter if the doors or any content in the box become loose in the payload bay.	
REDUNDANCY SCREENS	RECOMMENDED PATHS		INTERFACE	
A - Pass B - N/A C - Pass	1) Release 5/16" hex-head bolts at hinge.		None	
MISSION PHASE	CORRECTIVE ACTION TIMES			
	TIME TO EFFECT	TIME TO CORRECT		
EVA	Hours	Minutes		

PREPARED BY: J.F. PARK

REVISION: BASIC

SUPERSEDING DATE: NONE

DATE: 07/10/00

## CRI1 ITEMS LIST

PAGE 5 OF 5

SUBSYSTEM: TOOL BOX  
EFFECTIVITY: ALL ORBITERSREFERENCE DESIGNATOR: TBA-2  
NAME / QUANTITY: BACK-UP PANEL ASSY. (2)  
DRAWING REFERENCE: 19161-2020730206PROJECT: HST  
LRU NAME / QUANTITY: BACK-UP PANEL ASSY. (2)  
LRU PART NUMBER: 10161-20207-01/20206-01

FAILURE MODE NUMBER HST-TBA-3-1		CRITICALITY 1R/2	FAILURE EFFECT	RETENTION RATIONALE
<b>FUNCTION</b>			<b>END ITEM</b> Cannot relock the back-up panels which prevents the lap panel from being closed and the doors from being shut.	<b>DESIGN</b>  <b>IV. Failure History</b> A. There have been no failures associated with the door panel latches or the door panel hinges.  <b>V. Operations</b> A. <b>Effects of Failure</b> Cannot relock the back-up panel which prevents the lap panel from being closed and the doors from being shut. B. <b>Crew Actions</b> To activate the redundant path, the EVA crew will attach the EVA power tool or wrench to disengage the 7/16" hex-head bolts at the door hinges and the check bar attachment location and remove the lap panel. C. <b>Training</b> As part of the certification testing, crews will evaluate the redundant systems during the thermal vacuum tests. Additional training will occur in the WETF. D. <b>Mission Constraints</b> All contents in the box will have to be removed prior to landing in addition to the process listed in the crew actions section. E. <b>Inflight Check-Outs</b> None.
<b>FAILURE MODE AND CAUSE</b> <b>MODE</b> Either back-up panel is stuck in the deployed position.  <b>CAUSE(S)</b> 1) Latches are jammed closed. 2) Contamination.			<b>MISSION</b> Mission objectives are complete.	
REduNDANCY SCREENS A - Pass. B - N/A C - Pass	REMAINING PATHS 1) Release 5/16" hex-head bolts at hinge.		<b>CREW / VEHICLE</b> Possible damage to the orbiter if the doors or any content in the box become loose in the payload bay.	<b>INTERFACE</b> None
MISSION PHASE	CORRECTIVE ACTION TIMES			
	TIME TO EFFECT	TIME TO CORRECT		
EVA	Hours	Minutes		

PREPARED BY: J. P. PARK

REVISION: BASIC

SUPERSEDING DATE: NONE

DATE: 8/18/06

HST-TBA-1-23