

FAILURE MODES EFFECTS ANALYSIS (FMEA) - CIL HARDWARE

NUMBER: 05-6N-2073 -X

SUBSYSTEM NAME: EPD&C - AUXILIARY POWER UNIT (04-2)

REVISION: 2

01/13/94

PART DATA

	PART NAME VENDOR NAME	PART NUMBER VENDOR NUMBER
LRU	: AFT LCA 1	MC450-0057-0001
LRU	: AFT LCA 2	MC450-0058-0001
LRU	: AFT LCA 3	MC450-0059-0001
SRU	: CONTROLLER, HYBRID DRIVER	MC477-0263-0002

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:

CONTROLLER, HYBRID DRIVER, HDC TYPE 3 - AUXILIARY POWER UNIT (APU) HEATERS,
GAS GENERATOR 1, 2, AND 3 POWER CIRCUITS

REFERENCE DESIGNATORS: 54V76A121AR(J10-I)
54V76A121AR(J10-AA)
55V76A122AR(J10-I)
55V76A122AR(J10-AA)
56V76A123AR(J10-I)
56V76A123AR(J10-AA)

QUANTITY OF LIKE ITEMS: 6

SIX

FUNCTION:

CONDUCTS POWER TO APU 1, 2, AND 3 GAS GENERATOR HEATERS.

FAILURE MODES EFFECTS ANALYSIS FMEA - NON-CIL FAILURE MODE

NUMBER: 05-6N-2073- 02

REVISION#: 03 08/01/96

SUBSYSTEM NAME: EPD&C - AUXILIARY POWER UNIT (04-2)

LRU: AFT LCA 1, 2, 3

CRITICALITY OF THIS

ITEM NAME: CONTROLLER, HYBRID DRIVER

FAILURE MODE: 1R3

FAILURE MODE:

INADVERTENT OUTPUT, FAILS "ON", FAILS TO TURN "OFF"

MISSION PHASE: PL PRE-LAUNCH
 LO LIFT-OFF
 DO DE-ORBIT
 LS LANDING/SAFING

VEHICLE/PAYLOAD/KIT EFFECTIVITY: 102 COLUMBIA
 103 DISCOVERY
 104 ATLANTIS
 105 ENDEAVOUR

CAUSE:

PIECE PART STRUCTURAL FAILURE, CONTAMINATION, VIBRATION, MECHANICAL SHOCK, PROCESSING ANOMALY, THERMAL STRESS

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

REDUNDANCY SCREEN A) PASS
 B) N/A
 C) PASS

PASS/FAIL RATIONALE:

A)

B)

"DRIVER IS 2-FAULT TOLERANT WITH 2 REMAINING LEGS VERIFIABLE IN FLIGHT. INJECTOR COOLING OPERABILITY IS VERIFIABLE IN FLIGHT (THOUGH NOT PERFORMED). STATUS OF REMAINING APUS IS VERIFIABLE IN FLIGHT."

C)

- FAILURE EFFECTS -

(A) SUBSYSTEM:

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- NON-CIL FAILURE MODE
NUMBER: 05-6N-2073- 02

(B) INTERFACING SUBSYSTEM(S):
NO EFFECT - FIRST FAILURE.

(C) MISSION:
NO EFFECT - FIRST FAILURE

(D) CREW, VEHICLE, AND ELEMENT(S):
NO EFFECT - FIRST FAILURE

(E) FUNCTIONAL CRITICALITY EFFECTS:
POSSIBLE LOSS OF CREW/VEHICLE AFTER THREE OTHER FAILURES (HDC-4 FAILED ON, INJECTOR COOLING FAILED, LOSS OF SECOND APU) DUE TO LOSS OF TWO OF THREE APUS.

-DISPOSITION RATIONALE-

(A) DESIGN:
REFER TO APPENDIX B, ITEM NO. 1 - HYBRID DRIVER

(B) TEST:
REFER TO APPENDIX B, ITEM NO. 1 - HYBRID DRIVER

GROUND TURNAROUND TEST APU 1/2/3 FUEL PUMP AND GAS GENERATOR HEATER CIRCUIT TESTS PERFORMED EVERY OMDP.

(C) INSPECTION:
REFER TO APPENDIX B, ITEM NO. 1 - HYBRID DRIVER

(D) FAILURE HISTORY:
REFER TO APPENDIX B, ITEM NO. 1 - HYBRID DRIVER

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- NON-CIL FAILURE MODE
NUMBER: 05-6N-2073- 02

(E) OPERATIONAL USE:
NONE

- APPROVALS -

EDITORIALLY APPROVED : RI
EDITORIALLY APPROVED : JSC
TECHNICAL APPROVAL : VIA JSC

James G. Adams 8/27/96
Sam Leroy 8-27-96
96-CIL-010