

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL HARDWARE

NUMBER: M8-1MR-BM012-X

SUBSYSTEM NAME: MECHANICAL - EDS

REVISION: 2 9/1/95

	PART NAME VENDOR NAME	PART NUMBER VENDOR NUMBER
LRU	: DOCKING MECHANISM NPO-ENERGIA	MC621-0087-0001 MC621-0087-0001
SRU	: SEAL, PRESSURE NPO-ENERGIA	D410223802 D410223802
	: SEAL, PRESSURE NPO-ENERGIA	D410223803 D410223803

PART DATA

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:
DOCKING BASE/MECHANISM PRESSURE SEAL (LINER)

REFERENCE DESIGNATORS:

QUANTITY OF LIKE ITEMS: 4
FOUR

FUNCTION:

A SEAL (LINER) LOCATED ON THE INNER AND OUTER GROOVES AT TWO PLACES: (1) BETWEEN THE ORBITER DOCKING MECHANISM AND MIR DOCKING MECHANISM; AND (2) BETWEEN THE EXTERNAL AIRLOCK UPPER CYLINDER (DOCKING MECHANISM BASE) AND ORBITER DOCKING MECHANISM. THESE SEALS PROVIDE A REDUNDANT MEANS OF PREVENTING LOSS OF HABITABLE VOLUME THROUGH THESE INTERFACES DURING IVA.

SERVICE IN BETWEEN FLIGHT AND MAINTENANCE CONTROL:
VISUAL INSPECTION, SERVICEABILITY CONTROL.

MAINTAINABILITY
REPAIR METHOD - REPLACEMENT.

REFERENCE DOCUMENTS: 33U.4114.004-05
33U.6201.008-05
33U.9914.006-05
V076-534000

**FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL FAILURE MODE
NUMBER: MR-1MR-BM012-01**

(B) INTERFACING SUBSYSTEM(S):

POTENTIAL LOSS OF PRESSURE IN CREW CABIN WITH 'A' HATCH OPEN UPON LOSS OF BOTH SEALS.

(C) MISSION:

NO EFFECT FIRST FAILURE. POSSIBLE EARLY MISSION TERMINATION IF FAILURE OF REDUNDANT SEAL OCCURS PRIOR TO COMPLETION OF IVA ACTIVITIES.

(D) CREW, VEHICLE, AND ELEMENT(S):

NO EFFECT FIRST FAILURE. POSSIBLE EXTERNAL LEAKAGE OF HABITABLE PRESSURE GIVEN SIMILAR FAILURE OF SECOND SEAL DURING ON-ORBIT OPERATIONS.

(E) FUNCTIONAL CRITICALITY EFFECTS:

FIRST FAILURE - NO EFFECT. LOSS OF REDUNDANCY ONLY.
SECOND FAILURE - WORST CASE. RAPID DECOMPRESSION IN HABITABLE VOLUMES. LOSS OF CONSUMABLES IN HABITABLE AREAS WITH ALL INTERNAL HATCHES OPEN. SAFETY OF CREW MEMBERS IS JEOPARDIZED UPON LOSS OF CONSUMABLES. EARLY MISSION FOLLOWING FAILURE OF SECOND SEAL. LOSS OF EVA CREW MEMBERS IF EVA IS REQUIRED OUT TUNNEL ADAPTER 'C' HATCH (MIR 1) OR OUT EXTERNAL AIRLOCK AFT HATCH (MULT-MIR) AND EXTERNAL AIRLOCK CANNOT BE REPRESSURIZED FOR RETURN TO CABIN (EVA CREW MEMBERS MUST REMAIN IN INTERNAL AIRLOCK UNTIL LANDING.) POTENTIAL LOSS OF PRESSURE IN MIR IF SECOND FAILURE OCCURS WHILE MIR HATCH IS OPEN.

DESIGN CRITICALITY (PRIOR TO DOWNGRADE, DESCRIBED IN (F)): 1R2

(F) RATIONALE FOR CRITICALITY DOWNGRADE:

THIRD AND FOURTH FAILURE (INABILITY TO CLOSE APPROPRIATE HATCHES) - LOSS OF CAPABILITY TO ISOLATE LEAK FROM CREW CABIN. POSSIBLE LOSS OF CREW AND VEHICLE DUE TO INCREASED USE OF CONSUMABLES.

- TIME FRAME -

TIME FROM FAILURE TO CRITICAL EFFECT: HOURS TO DAYS

TIME FROM FAILURE OCCURRENCE TO DETECTION: SECONDS

TIME FROM DETECTION TO COMPLETED CORRECTIVE ACTION: SECONDS TO MINUTES

**IS TIME REQUIRED TO IMPLEMENT CORRECTIVE ACTION LESS THAN TIME TO EFFECT?
YES**

RATIONALE FOR TIME TO CORRECTING ACTION VS TIME TO EFFECT:

CREW HAS AMPLE TIME TO CLOSE APPROPRIATE HATCH(S) TO ISOLATE THE LEAK FROM THE CREW CABIN.

HAZARDS REPORT NUMBER(S): ORBI 511

HAZARD(S) DESCRIPTION:


LOSS OF PRESSURE IN HABITABLE VOLUME.

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL FAILURE MODE
NUMBER: M8-1MR-BM012-01

- APPROVALS -

DESIGN ENGINEER
DESIGN MANAGER

: M. NIKOLAYEVA
: A. SOUBCHEV

: 
: 
