

**FAILURE MODES EFFECTS ANALYSIS (FMEA) – CIL HARDWARE**  
**NUMBER:04-2-RV02 -X**

**SUBSYSTEM NAME:** AUXILIARY POWER UNIT (APU)

**REVISION:** 1 09/17/98

**PART DATA**

	<b>PART NAME</b>	<b>PART NUMBER</b>
	<b>VENDOR NAME</b>	<b>VENDOR NUMBER</b>
LRU	:RELIEF VALVE WRIGHT COMPONENTS	ME284-0544 0002/0003 11292-1/-2

**EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:**

RELIEF VALVE IS IN THE APU FUEL PUMP SEAL CAVITY DRAIN SYSTEM BETWEEN THE BURST DISK AND OVERBOARD VENT AND RELIEVES AT 28 TO 42 PSIA.

**QUANTITY OF LIKE ITEMS:** 3  
ONE PER APU

**FUNCTION:**

CONTAINS AND RELIEVES THE PRESSURE AT 28 TO 42 PSIA IN THE APU FUEL PUMP SEAL CAVITY DRAIN SYSTEM IF SUFFICIENT FUEL HAS LEAKED THROUGH THE PUMP SEAL TO CRACK THE OVERBOARD RELIEF VALVE.

**FAILURE MODES EFFECTS ANALYSIS FMEA -- NON-CIL FAILURE MODE**

NUMBER: 04-2-RV02-01

REVISION#: 1 09/02/98

SUBSYSTEM NAME: AUXILIARY POWER UNIT (APU)

LRU: RELIEF VALVE

ITEM NAME: RELIEF VALVE

CRITICALITY OF THIS

FAILURE MODE: 1R3

**FAILURE MODE:**  
FAILS TO RELIEVE

**MISSION PHASE:**

PL	PRE-LAUNCH
LO	LIFT-OFF
OO	ON-ORBIT
DO	DE-ORBIT
LS	LANDING/SAFING

**VEHICLE/PAYLOAD/KIT EFFECTIVITY:**

102	COLUMBIA
103	DISCOVERY
104	ATLANTIS
105	ENDEAVOUR

**CAUSE:**  
CONTAMINATION

**CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO**

**REDUNDANCY SCREEN**

A) PASS
B) N/A
C) PASS

**PASS/FAIL RATIONALE:**

**A)**  
RELIEF VALVE CAN BE FUNCTIONALLY TESTED THROUGH THE TEST PORT ON THE BURST DISK AT VEHICLE TURN AROUND.

**B)**  
N/A - STANDBY REDUNDANT ITEM

**C)**  
A SINGLE CREDIBLE FAILURE EVENT CANNOT CAUSE LOSS OF ALL RELIEF VALVE REDUNDANCY

**- FAILURE EFFECTS -**

**(A) SUBSYSTEM:**  
NONE FOR THE FIRST FAILURE

**(B) INTERFACING SUBSYSTEM(S):**

**FAILURE MODES EFFECTS ANALYSIS (FMEA) -- NON CIL FAILURE MODE  
NUMBER: 04-2-RV02-01**

NONE FOR THE FIRST FAILURE.

**(C) MISSION:**

NONE WITHOUT ADDITIONAL FAILURES

**(D) CREW, VEHICLE, AND ELEMENT(S):**

NONE WITHOUT ADDITIONAL FAILURES.

**(E) FUNCTIONAL CRITICALITY EFFECTS:**

POSSIBLE LOSS OF CREW/VEHICLE AFTER THREE FAILURES:

- (1) A GROSS LEAK AT AN APU FUEL PUMP SHAFT SEAL.
- (2) FAILED CLOSED RELIEF VALVE MAY RESULT IN SUFFICIENT INCREASE OF THE CATCH BOTTLE PRESSURE TO CAUSE THE INTRUSION OF HYDRAZINE INTO THE GEARBOX RESULTING IN WAX FORMATION (POSSIBLE APU LOSS).
- (3) LOSS OF ONE OF THE TWO REMAINING APU'S COULD POSSIBLY CAUSE LOSS OF CREW/VEHICLE.

**- APPROVALS -**

SS & PAE MANAGER	for D. F. MIKULA
SS & PAE ENGINEER	: K. E. RYAN
VEHICLE & SYSTEMS DESIGN	: M. A. WEISER
BNA SSM	: T. FARKAS, JR.
JSC MOD	: M. FRIANT
JSC NASA SROA	: D. BEAUGH
USA/SAM	: A. BUCHHEIT

*[Signature]*  
*[Signature]*  
*[Signature]*  
*[Signature]*  
*[Signature]*  
*[Signature]* 11/4/98  
*[Signature]* 11/4/98

*[Signature]* 11/6/98