

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL HARDWARE
NUMBER: 05-6-2658 -X

SUBSYSTEM NAME: ELECTRICAL POWER DISTRIBUTION & CONTROL
REVISION: 0 **05/03/88**

PART DATA

	PART NAME	PART NUMBER
	VENDOR NAME	VENDOR NUMBER
LRU	: PANEL R13A2	V070-730338
SRU	: SWITCH, TOGGLE	ME452-0102-7401

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:
SWITCH, TOGGLE, 4P2P, HERMETICALLY SEALED - PAYLOAD BAY MECHANICAL POWER
"ON/OFF" CONTROL

REFERENCE DESIGNATORS: 32V73A13A2S1
 32V73A13A2S2

QUANTITY OF LIKE ITEMS: 2
TWO

FUNCTION:
PROVIDES THE CREW WITH THE CAPABILITY TO CONTROL "ON/OFF" ELECTRICAL
INPUTS TO PAYLOAD BAY MECHANICAL (PLBM) POWER BUS, SYSTEM 1 AND 2.

FAILURE MODES EFFECTS ANALYSIS FMEA -- CIL FAILURE MODE

NUMBER: 05-6-2658-01

REVISION#: 1 07/26/99

SUBSYSTEM NAME: ELECTRICAL POWER DISTRIBUTION & CONTROL

LRU: PANEL R13A2

CRITICALITY OF THIS

ITEM NAME: SWITCH, TOGGLE

FAILURE MODE: 1R2

FAILURE MODE:

FAILS OPEN, PREMATURELY OPENS, SHORTS TO GROUND

MISSION PHASE: OO ON-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY:	102	COLUMBIA
	103	DISCOVERY
	104	ATLANTIS
	105	ENDEAVOUR

CAUSE:

PIECE PART STRUCTURAL FAILURE, CONTAMINATION, MECHANICAL SHOCK, VIBRATION, PROCESSING ANOMALY

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

REDUNDANCY SCREEN	A) PASS
	B) PASS
	C) PASS

PASS/FAIL RATIONALE:

A)

B)

PASSES "B" SCREEN BECAUSE FAILURE CAN BE DETECTED WHEN USE OF THE PLBM BUS IS REQUIRED.

C)

- FAILURE EFFECTS -**(A) SUBSYSTEM:**

LOSS OF REDUNDANCY. LOSS OF PLBM POWER BUSES AC1, AC2 AND AC3 TO MID MCA'S 1 AND 2 OR 3 AND 4.

**FAILURE MODES EFFECTS ANALYSIS (FMEA) - CIL FAILURE MODE
NUMBER: 05-6-2658-01**

(B) INTERFACING SUBSYSTEM(S):

LOSS OF INTERFACE REDUNDANCY. LOSS OF AC POWER FOR ONE OF TWO MOTORS FOR EACH PLBM FUNCTION.

(C) MISSION:

POSSIBLE EARLY MISSION TERMINATION

(D) CREW, VEHICLE, AND ELEMENT(S):

FIRST FAILURE - NO EFFECT

(E) FUNCTIONAL CRITICALITY EFFECTS:

SECOND FAILURE (LOSS OF OTHER PLBM POWER SWITCH) MAY RESULT IN THE LOSS OF THE FOLLOWING PLBM FUNCTIONS - FREON RADIATOR DEPLOY/STOW AND LATCH AND P/L RETENTION LATCHES. POSSIBLE LOSS OF CREW/VEHICLE IF RADIATORS CANNOT BE STOWED. FAILURE TO STOW RADIATORS MAY PRECLUDE SAFE RE-ENTRY DUE TO INABILITY TO CLOSE AND LATCH THE PAYLOAD BAY DOORS. FAILURE TO CLOSE AND LATCH THE PAYLOAD BAY DOORS RESULTS IN A LOSS OF ORBITER VEHICLE STRUCTURAL STIFFNESS AND POSSIBLE STRUCTURAL DAMAGE DUE TO AERODYNAMIC FORCES DURING DESCENT. EVA CAPABILITY EXISTS FOR WORKAROUND OF FAILURE OF PAYLOAD RETENTION LATCHES (CRIT 1R3).

-DISPOSITION RATIONALE-

(A) DESIGN:

REFER TO APPENDIX A, ITEM NO. 1 - TOGGLE SWITCH

(B) TEST:

REFER TO APPENDIX A, ITEM NO. 1 - TOGGLE SWITCH

GROUND TURNAROUND TEST

ANY TURNAROUND CHECKOUT TESTING IS ACCOMPLISHED IN ACCORDANCE WITH OMRSD.

(C) INSPECTION:

REFER TO APPENDIX A, ITEM NO. 1 - TOGGLE SWITCH

(D) FAILURE HISTORY:

**FAILURE MODES EFFECTS ANALYSIS (FMEA) – CIL FAILURE MODE
NUMBER: 05-6-2858-01**

CURRENT DATA ON TEST FAILURES, FLIGHT FAILURES, UNEXPLAINED ANOMALIES, AND OTHER FAILURES EXPERIENCED DURING GROUND PROCESSING ACTIVITY CAN BE FOUND IN THE PRACA DATA BASE.

(E) OPERATIONAL USE:
CONSIDERATION MAY BE GIVEN TO SECURING MECHANISMS AFTER FIRST FAILURE.

- APPROVALS -

EDITORIALLY APPROVED	: BNA	: <u>J. Komura 7-26-99</u>
TECHNICAL APPROVAL	: VIA APPROVAL FORM	: 96-CIL-025_05-6