

**FAILURE MODES EFFECTS ANALYSIS (FMEA) – NON-CIL HARDWARE
NUMBER: 05-6-2756 -X**

**SUBSYSTEM NAME: ELECTRICAL POWER DISTRIBUTION & CONTROL
REVISION: 1 07/26/98**

PART DATA

	PART NAME VENDOR NAME	PART NUMBER VENDOR NUMBER
LRU	: MID MCA-4	V070-764500
LRU	: MID MCA-4	V070-764640
SRU	: RELAY, GENERAL PURPOSE	MC455-0129-0001

**EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:
RELAY, GENERAL PURPOSE, 4 POLE - MID MCA 4 THREE-PHASE PLBM AC BUS 2**

REFERENCE DESIGNATORS: 40V76A120K49
40V76A120K61

QUANTITY OF LIKE ITEMS: 2
TWO

FUNCTION:
UPON CREW INITIATED SWITCH COMMANDS, THE CONTACTS OF TWO SERIES RELAYS CONNECT MID MOTOR CONTROL ASSEMBLY #4 AC BUS AC2 (PHASE A, B, AND C) TO PAYLOAD BAY MECHANICAL (PLBM) AC BUS 2 FOR FREON RADIATOR LATCH, REMOTE MANIPULATOR LATCH AND KU-BAND DEPLOY/STOW MOTORS.

SHUTTLE CRITICAL ITEMS LIST - ORBITER

SUBSYSTEM :ELECT POWER DIST & CONT FMEA NO 05-6 -2756 -2 REV:05/03/88

ASSEMBLY :M-MCA-4	CRIT.FUNC: 1R
P/N RI :MC455-0129-0001	CRIT. HDW: 2
P/N VENDOR:	VEHICLE 102 103 104
QUANTITY :2	EFFECTIVITY: X X X
:TWO	PHASE(S): PL LO OO X DO X LS
:	

REDUNDANCY SCREEN: A-PASS B-PASS C-PASS

PREPARED BY:	APPROVED BY:	APPROVED BY (NASA):
DES R PHILLIPS	DES <i>R. Burns</i>	SSM <i>W. C. ... 5/12/88</i>
REL M HOVE	REL <i>M. ... 5-6-88</i>	REL <i>D. ... 5/12/88</i>
QE J COURSEN	QE <i>J. J. Coursem 5/6/88</i>	QE <i>R. ... 5/12/88</i>

ITEM:

RELAY, GENERAL PURPOSE, 4 POLE - MID MCA 4 THREE-PHASE PLBM AC BUS 2

FUNCTION:

UPON CREW INITIATED SWITCH COMMANDS, THE CONTACTS OF TWO SERIES RELAYS CONNECT MID MOTOR CONTROL ASSEMBLY #4 AC BUS AC2 (PHASE A, B, AND C) TO PAYLOAD BAY MECHANICAL (PLBM) AC BUS 2 FOR FREON RADIATOR LATCH, REMOTE MANIPULATOR LATCH AND KU-BAND DEPLOY/STOW MOTORS. 40V76A120K49 AND K61

FAILURE MODE:

SHORTS TO GROUND (CONTACT), SHORT POLE-TO-POLE

CAUSE(S):

PIECE PART FAILURE, VIBRATION, MECHANICAL SHOCK, PROCESSING ANOMALY

EFFECT(S) ON:

(A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE (E)FUNCTIONAL CRITICALITY EFFECT:

(A) LOSS OF MID MOTOR CONTROL ASSEMBLY #4 THREE-PHASE AC BUS 2 DUE TO TRIPPING OF CB9 ON PANEL MA73C. RESULTS IN LOSS OF PLBM AC BUS 2 AND PLBD AC BUS 2.

(B) LOSS OF REDUNDANCY FOR FUNCTIONS POWERED BY AC BUS 2 IN MID MOTOR CONTROL ASSEMBLY #4. ALL CRITICAL FUNCTIONS HAVE REDUNDANT MOTORS POWERED FROM A DIFFERENT AC BUS IN A DIFFERENT MID MOTOR CONTROL ASSEMBLY.

(C) POSSIBLE EARLY MISSION TERMINATION WITH LOSS OF REDUNDANCY FOR CLOSING PAYLOAD BAY DOORS.

(D) FIRST FAILURE - NO EFFECT.

SHUTTLE CRITICAL ITEMS LIST - ORBITER

DBSYSTEM :ELECT POWER DIST & CONT FMEA NO 05-6 -2756 -2 REV:05/03/88

EFFECT(S) ON (CONTINUED):

(A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE (E)FUNCTIONAL
CRITICALITY EFFECT:

(E) POSSIBLE LOSS OF CREW/VEHICLE AFTER SECOND FAILURE (LOSS OF
REDUNDANT MOTOR OR POWER/CONTROL CIRCUIT) DUE TO INABILITY TO CLOSE
PAYLOAD BAY DOORS (RESULTING IN AERODYNAMIC STRUCTURAL DAMAGE DURING
ENTRY) AND/OR TO OPEN VENT DOORS DURING DESCENT (DOOR FAILED CLOSED
RESULTS IN VEHICLE STRUCTURAL DAMAGE DUE TO PRESSURE DIFFERENTIALS).
LEFT AND RIGHT VENT DOORS ARE NOT CONSIDERED TO BE REDUNDANT TO EACH
OTHER. "B" SCREEN PASSES SINCE THE FAILURE CAN BE DETECTED BY CREW
MONITORING MECHANISM OPERATION TIMES.

DISPOSITION & RATIONALE:

(A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY (E)OPERATIONAL USE

A, B, C, D) DISPOSITION AND RATIONALE

REFER TO APPENDIX C, ITEM NO. 2 - GENERAL PURPOSE RELAY

B) GROUND TURNAROUND TEST

VERIFY MCA OPERATIONAL STATUS INDICATORS ARE "ON" (ALL MOTOR CONTROL
RELAYS RESET) DURING NO OPERATION OF THE AC MOTOR MECHANISMS. TEST IS
PERFORMED FOR ALL FLIGHTS.

E) OPERATIONAL USE

CONSIDERATION WILL BE GIVEN TO STOWING MECHANISMS WITH THE LOSS OF
REDUNDANCY. LOSS OF REDUNDANT PAYLOAD BAY DOOR CLOSE CAPABILITY
INVOKES A MINIMUM DURATION FLIGHT. FOR LOSS OF REDUNDANT VENT DOOR
OPEN CAPABILITY, OPEN VENT DOORS PRIOR TO ENTRY.