

CRITICAL ITEMS LIST (CIL)

SYSTEM: ASI
 SUBSYSTEM: Nose Cone Assembly
 REV & DATE: J, 12-19-97
 DCN & DATE:
 ANALYSTS: L. Hansen/E. Howell

FUNCTIONAL CRIT: 1
 PHASE(S): b
 HAZARD REF: S.11

FAILURE MODE: Structural Failure
 FAILURE EFFECT: b) Loss of mission and vehicle/crew due to LO2 tank structural failure or debris source to orbiter.
 TIME TO EFFECT: Immediate
 FAILURE CAUSE(S): A: Improper Manufacture
 B: Failure of Attaching Hardware
 REDUNDANCY SCREENS: Not Applicable
 FUNCTIONAL DESCRIPTION: Provides aerodynamic shape for nose cone tip and lightning protection.

<u>FMEA ITEM CODE(S)</u>	<u>PART NO.</u>	<u>PART NAME</u>	<u>QTY</u>	<u>EFFECTIVITY</u>
4.1.1.1	80911041207-010 -019	Spike Assembly	1	LWT-54 thru 80, 82-84
			1	LWT-81, 85 & Up

REMARKS:

CRITICAL ITEMS LIST (CIL)
CONTINUATION SHEET

SYSTEM: ASI
SUBSYSTEM: Nose Cone Assembly
FMEA ITEM CODE(S): 4.1.1.1

REV & DATE: J, 12-19-97
DCN & DATE:

RATIONALE FOR RETENTION

DESIGN:

- A, B: The 80911041207 spike is a double conic aluminum casting 14.01 inches long.
- The spike is attached to the nose cone assembly by six mounting bolts through the base of the casting. Materials are selected in accordance with MMC-ET-SE16 which requires repetitive conformance of composition and properties. The spike and attachment hardware are designed to the required ultimate safety factor of 1.4 (ET Stress Report 826-2188).
- B: Attaching hardware is selected from the Approved Standard Parts List (ASPL 826-3500), installed per STP2014 and torqued using values specified on Engineering drawings. Tensile installation loads are sufficient to provide screening for major flaws in individual fasteners.

TEST:

The Spike Assembly is certified. Reference HCS MMC-ET-TM08-L-5001.

Vendor:

- B: Attaching hardware is procured and tested to Standard drawings (26L3 and 34L1).

INSPECTION:

Vendor Inspection - Lockheed Martin Surveillance:

- A, B: Verify materials selection and verification controls (MMC-ET-SE16 and Standard drawing 34L1; drawing 82611001800 and Standard drawings 26L3 for LWT 82 thru 84 and prior to LWT-81; drawings 82611001800 and NAS6704U for LWT-81, 85 & up).
- A: Inspect dimensions (drawing 80911041207).

MAF Quality Inspection:

- B: Inspect that attaching hardware is free from damage (STP2014; drawing 80911041201 for LWT-82 thru 84 and prior to LWT-81; drawing 80911041231 for LWT-81, 85 & up).
- A, B: Verify installation and witness torque (drawing 80911041201 for LWT 82 thru 84 and prior to LWT-81; drawing 80911041231 for LWT-81, 85 & up).
- B: Verify insert locking feature (STP2014; drawing 80911041201 for LWT 82 thru 84 and prior to LWT-81; drawing 80911041231 for LWT-81, 85 & up).

FAILURE HISTORY:

Current data on test failures, unexplained anomalies and other failures experienced during ground processing activity can be found in the PRACA data base.