

SHUTTLE CRITICAL ITEMS LIST - ORBITER

SUBSYSTEM : EPD&C - MAIN PROP. FMEA NO 05-6J -2090 -1 REV: 04/28/88 ^{5/5}
 ASSEMBLY : AFT LCA - 2, 3 CRIT. FUNC: 1R
 P/N RI : MC477-0263-0002 CRIT. HDW: 2
 P/N VENDOR: VEHICLE 102 103 104
 QUANTITY : 2 EFFECTIVITY: X X X
 : TWO PHASE(S): PL X LO X OO DO LS
 :

REDUNDANCY SCREEN: A-PASS B-FAIL C-PASS

PREPARED BY: APPROVED BY: APPROVED BY (NASA):
 DES J BROWN DES A Burns EPDC SSM [Signature]
 REL F DEFENSOR REL [Signature] MPS SSM [Signature]
 QE D MASAI QE G.D. Couser 5-6-88 EPDC REL [Signature]
 MPS REL [Signature]

ITEM: CONTROLLER, HYBRID DRIVER (HDC), TYPE III, LO2 OVERBOARD BLEED VALVE CLOSE SOLENOID (LV76).

FUNCTION:

CONDUCTS POWER TO CLOSE SOLENOID IN EACH REDUNDANT CIRCUIT FOR LO2 OVERBOARD BLEED VALVE. HDC IS IN SERIES WITH A DIODE AND RPC IN EACH CIRCUIT. 55V76A122ARJ3(55), 56V76A123ARJ3(54).

FAILURE MODE:

LOSS OF OUTPUT, FAILS TO CONDUCT, FAILS TO TURN "ON".

CAUSE(S):

PIECE PART FAILURE, CONTAMINATION, VIBRATION, MECHANICAL SHOCK, PROCESSING ANOMALY, THERMAL STRESS.

EFFECT(S) ON:

(A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE (E) FUNCTIONAL CRITICALITY

(A) LOSS OF ONE OF TWO POWER PATHS TO LO2 OVERBOARD BLEED VALVE CLOSE SOLENOID. DEGRADATION OF REDUNDANCY AGAINST INADVERTENT DEACTUATION OF CLOSE SOLENOID.

(B,C,D) NO EFFECT - FIRST FAILURE.

SHUTTLE CRITICAL ITEMS LIST - ORBITER

SUBSYSTEM : EPD&C - MAIN PROP.

FMEA NO 05-6J -2090 -1

REV: 04/26/88

5/5
DEF 5-12

(E) CASE I: 1R/2, 1 SUCCESS PATH AFTER FIRST FAILURE.

TIME FRAME - PRELAUNCH.

1) HDC FAILS "OFF".

2) PARALLEL POWER PATH FAILS "OFF" (HDC, RPC, DIODE) CAUSING LO2 OVERBOARD BLEED VALVE (PV19) TO OPEN.

FAILURES WILL RESULT IN CONTINUED BLEED FLOW RESULTING IN LOSS OF LO2 OVERBOARD WITH FAILURE OF BLEED DISCONNECT (PD13) TO CLOSE. BLEED DISCONNECT IS NOT CERTIFIED FOR CLOSURE UNDER FLOW CONDITIONS AND CANNOT BE CONSIDERED A REDUNDANT INHIBIT AGAINST OVERBOARD FLOW. POSSIBLE RUPTURE OF DISCONNECT HOUSING AND/OR DOWNSTREAM BLEED SYSTEM DUE TO WATER HAMMER. RESULTS IN LOSS OF APPROXIMATELY 3000 LBS OF PROPELLANT WHICH IS INSUFFICIENT TO CAUSE PREMATURE SSME SHUTDOWN.

POSSIBLE AFT COMPARTMENT OVERPRESSURIZATION. FIRE/EXPLOSIVE HAZARD BOTH INTERIOR AND EXTERIOR TO THE VEHICLE. NO LCC EXISTS FOR VERIFICATION OF VALVE POSITION PRIOR TO T-0. POSSIBLE LOSS OF CREW/VEHICLE.

FAILS B SCREEN BECAUSE PARALLEL POWER PATH MASKS FAILURE.

CASE II: 1R/3, 2 SUCCESS PATHS AFTER FIRST FAILURE.

TIME FRAME - ASCENT.

1) HDC FAILS "OFF".

2) PARALLEL POWER PATH FAILS "OFF" (HDC, RPC, DIODE) CAUSING LO2 OVERBOARD BLEED VALVE (PV19) TO OPEN.

3) BLEED DISCONNECT (PD13) FAILS TO CLOSE/REMAIN CLOSED.

RESULTS IN LOSS OF APPROXIMATELY 3000 LBS. OF PROPELLANT WHICH IS NOT ENOUGH TO CAUSE PREMATURE SSME SHUTDOWN. POSSIBLE FIRE/EXPLOSION HAZARD IN FLIGHT. POSSIBLE LOSS OF CREW/VEHICLE.

FAILS B SCREEN BECAUSE PARALLEL POWER PATH MASKS FAILURE.

DISPOSITION & RATIONALE:

(A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY (E) OPERATIONAL USE

(A-D) FOR DISPOSITION AND RATIONALE

REFER TO APPENDIX B, ITEM NO. 1 - HYBRID DRIVER CONTROLLER.

(B) GROUND TURNAROUND TEST

COMPLETE ELECTRICAL VERIFICATION V41ABO.200C,D EVERY FLIGHT.

(E) OPERATIONAL USE

NO CREW ACTION CAN BE TAKEN.

INSERT

DEF 5-13

05-6J-158

INSERT FOR CIL 05-6J-2090-1
EFFECTS SECTION (E)

IF THE LO2 BLEED VALVE FAILS TO CLOSE BEFORE T-0 THE LO2 BLEED DISCONNECT WOULD BE CLOSING WITH AN OXYGEN FLOW OF 4.1 LBS/SEC. THIRTY-TWO PERCENT OF THIS FLOW WILL BE VAPOR. THE LO2 BLEED DISCONNECT IS NOT CERTIFIED FOR CLOSURE UNDER FLOW. HOWEVER, THE CLOSURE IS AT ONE "G" ACCELERATION RATE (T-0 UMBILICAL SEPARATION RATE) WHICH LIMITS THE IMPACT ENERGY ON THE VESPEL SEAL TO A LEVEL WHICH IS BELOW THE LO2/VESPEL IGNITION LEVEL (NOT PREVIOUSLY TESTED WITH THIS CONDITION). THE WATER HAMMER TOWARDS EFFECT GENERATED DURING THIS CLOSURE HAS BEEN CALCULATED TO BE APPROXIMATELY 60 PSIG. SYSTEM PROOF PRESSURE LEVEL IS 286 PSIG.

05-6J-159