

EXECUTIVE RISK ASSESSMENT SUMMARY

HAZARD REPORT NUMBER: LWS-MS-ERAS-4A	DATE: 12/95
REV. LETTER:	REV. DATE:
PART NUMBER: 950001-1	LRU NUMBER: SED39126815
TITLE: Unable to release crew from restraint system.	1. SEVERITY: Catastrophic 2. LIKELIHOOD OF OCCURRENCE: Improbable 3. CLASSIFICATION: Controlled
CAUSE: A. Restraint system inertia reel fails to release.	REDUNDANCY SCREENS: A - Pass B - Pass C - Pass
FMEA: LWS-MS-ERAS-4A Criticality: 1R/2 Name/Quantity: Inertia reel/1 Function: Restrains crew member's upper torso. Failure Mode: Internal components of inertia reel fail resulting in no movement of upper torso restraint.	Cause: Contamination, excessive use, piece-part defect Failure detection: Crew notices no movement of shoulder belts.
Corrective Action: Manually adjust shoulder tension using shoulder adjustment buckle	
EFFECT: Time to Effect: Immediate Time to Correct: Failure Effect: Inertia reel not capable of providing tension adjustment of shoulder belt. Possible crew member injury.	REMAINING PATHS: 1. Shoulder belt manual adjustment buckle
CONTROL/RETENTION RATIONALE: 1. Designed for minimum access for contamination. 2. Functional test performed before and after each certification test, PDA (SKD39126824), PIA (SKD39126825) and OMRS (File 3 V66AAO) with QA participation during each certification test, PDA and PIA. 3. Restraint system harness will be designed to withstand vibrational loads associated with Launch, RTLS and Landing.	

EXECUTIVE RISK ASSESSMENT SUMMARY

VERIFICATION:

1. During assembly all parts are checked to be clean.
- 2a. PDA 4.2.8.10, PLA 4.2.8.10 Verify the inertia reel manual lock functionality. Move the inertia reel controller to manual lock position. The inertia reel shall prevent the lead-in strap from extending more than 1/2 inch when pulled forward. Allow the inertia reel to partially retract the lead-in strap from its previous position. As before, the inertia reel shall limit travel to 1/2 inches or less.
- 2b. PDA 4.2.8.12, PLA 4.2.8.12 Verify the inertia reel automatic lock functionality. Extend the lead-in strap approximately nine inches with the inertia reel controller in the automatic lock position. Hold the lead-in strap with one hand and strike the strap sharply with the other hand. The inertia reel shall lock the strap with a maximum payout of 1.5 inches or less. Slowly release the lead-in strap to eliminate the load. The inertia reel shall then fully retract the lead-in strap.
- 2c. OMRS V66AA0.052-C, 053-C, 054-C, 055-C, 056-C - Position inertia reel manual lever in lock position and verify normal operation. Retract normally yet cannot extend more than 1/2 inch.
3. A vibration test has been performed (QVT TPS FV9520103) to the acceptance levels listed below and reviewed by EM2:

Frequency Range (Hz)	Level			
20	0.00053 g ² /Hz	1000	0.030 g ² /Hz	Overall = 6.1 grms
150	0.030 g ² /Hz	2000	0.0075 g ² /Hz	
350	0.040 g ² /Hz			