

STS-112
FLIGHT READINESS REVIEW
Department of Defense

September 17, 2002

SUPPORT POSTURE	

- Augmented Landing Site (ALS) Contingency Support
 - No known shortfalls
- Emergency Landing Site (ELS) Contingency Support
 - No known shortfalls
- DOD General Support
 - No known shortfalls



DOD READINESS CERTIFICATION	

DOD contingency forces are ready to support
Launch Program Requirements

S/David K. Dingley

DAVID K. DINGLEY
Colonel, USAF
Commander, DOD Manned Space
Flight Support Office

