



jsc2003e54128 Photo by Bill Stafford

In This Issue

Director's Message

2

Combined Federal Campaign

3

Return to Flight: Thermal Protection System repair

4-5

NASA Engineering and Safety Center

6

Corporate College Recruitment Initiative

7

JSC People Profiles

8

Seeking solutions

The KC-135 aircraft provided a microgravity environment for rehearsing spacewalk activity tasks for repairing damaged Shuttle tiles. Here, Astronaut Scott Parazynski injects the cure-in-place ablator into a damaged section of thermal tiles.

For more information about Johnson Space Center's role in NASA's Return to Flight Implementation Plan, please see pages 4-5.